Technical Service Bulletin

01 MIL on (DTC P033100 or P033200) in ECM - Repair Authorization

01 13 88 2033766/1 May 2, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6/A7	2012-2013	All	3.0 FSI Engine

Condition

- MIL on.
- One or both of the following DTCs are stored in the engine control module, J623 (address word 01):
  - **DTC P03300** (Knock Sensor 2 Circuit Range/Performance)
  - **DTC P033200** (Knock Sensor 2 Circ. Low Input)

Technical Background

Not applicable.

Production Solution

No changes in production have been made, as no issues have been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

1. Verify that **DTC P033100** and/or **DTC P033200** is stored in memory.
2. Do **not** disconnect any connectors and **do not** delete the DTCs.
3. Contact a TAC consultant before proceeding.
4. Attach the DTC and diagnostic log to the TAC ticket.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

© 2013 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2013 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.