Connection offline

**Technical Service Bulletin** Transaction No.: **2080075/4**

34 Gearbox: drive system fault in instrument cluster, DTC P066700, symptom 20752, address: 0002 Release date: Sep 28, 2026

## Condition

| Model(s) | Year(s) | VIN Range | Vehicle Specific Equipment | | | |
|---|---|---|---|---|---|---|
| | | | 00A5 - Front sensor for driver assistance systems | | | |
| | | | **Software part number** | **Software version** | **Hardware part number** | **Hardware version** |
| A5, S5 (FU), Q5, Q5 Sportback, SQ5, and SQ5 Sportback (GU) | 2025 | All up to CW 36/25 | * | 0250 | * | * |
| | | | * | 0295 | * | * |

| REVISION HISTORY | | |
|---|---|---|
| **Revision** | **Date** | **Purpose** |
| 4 | - | Revised title (Updated for clarity)<br>Revised *Condition* (Updated model table)<br>Revised *Production Solution* (Updated verbiage)<br>Revised *Service* (Updated verbiage)<br>Revised *Warranty* (Updated labor operations) |
| 3 | 01/30/2026 | Revised header (Updated control units) |
| 2 | 12/18/2025 | Revised header (Add Model Year)<br>Revised *Condition* (Added revision history) |

**Customer states:**

- The drive system fault warning lamp lights up in the dash panel insert.

**and/or**

- There is no direct customer complaint.
- The event memory entry specified in the workshop findings is found in gearbox electronics control unit J217 in connection with a different complaint.

**Workshop findings:**

The following DTC and symptom code is logged in the transmission electronics control unit - J217- (diagnostic address 0002):

- **P066700:** “PCM/ECM/TCM Internal Temperature Sensor "A" Range/Performance” with symptom 20752.
- The customer only complained about a warning lamp lighting up.

## Technical Background

Not applicable.

## Production Solution

Not applicable.

## Service

Combined software update

The complaint is solved with the target combined software version 03.10.00/C [KD2]. This combined software package has already been rolled out.

Please note that the KD package may have been superseded by a subsequent combined software update.

All information about the current schedule and availability of the measure can be found in central service information TSB 2081477.

Please also note any changes in the warranty accounting instructions.

## Warranty

Billing is performed via the complaint related TSB. The service number and damage code from this complaint-related TSB must be stated when billing.

The TSB number must always be noted in the “HST number” field in SAGA/2 for ease of processing.

| | | | |
|---|---|---|---|
| **Claim Type:** | • If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only. | | |
| **Service Number:** | 3410 | | |
| **Damage Code:** | KD2S | | |
| **Labor Operations:** | Work for a combined software update. | Please refer to central service information TSB 2081477. | Please refer to central service information TSB 2081477. |
| **Claim Comment:** | As per TSB 2080075/4 | | |

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

The software must be updated on a control unit in this vehicle, or the software must be updated on several control units in this vehicle to ensure they function correctly in conjunction with the other control units in the vehicle. Please inform the customer about the software update in question and ask whether they or other third parties have modified the software, (e.g. tuning or retrofitting modifications to the vehicle’s software). Please inform the customer that this software update may neutralize previous modification to the software of the vehicle performed either by the customer or other third parties.

If the customer declines the software update, please inform them that this could lead to issues or restrictions with the use of the vehicle or individual components.

Make a note to this effect on the order before it is signed by the customer. Include this information in the customer file.

All part and service references provided in this TSB (**2080075**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

**©2026 Audi of America, LLC / Audi Canada Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.