Connection offline

Technical Service Bulletin Transaction No.: **2083309/1**

93 Electrical system: HV: electric drive system warning lamp lights up / event memory entry P0A2B00 (41505) - Q4 e-tron

Release date: Sep 17, 2026

Condition

<table>
<tr><th>Model(s)</th><th>Year(s)</th><th>VIN Range</th><th colspan="4">Vehicle Specific Equipment</th></tr>
<tr><td rowspan="5">Q4 e-tron, and Q4 Sportback e-tron</td><td rowspan="5">2026</td><td rowspan="5">All</td><td colspan="4">With PR Code:
V7A
OR
V7B
OR
V7C
OR
V7E
OR
V7G
OR
V7T</td></tr>
<tr><td colspan="4">0051 - Electric drive</td></tr>
<tr><td>Software part number</td><td>Software version</td><td>Hardware part number</td><td>Hardware version</td></tr>
<tr><td>*0ET*.*.*</td><td>7430</td><td>*0ET*.*.*</td><td>*</td></tr>
<tr><td>*0ET*.*.*</td><td>7300</td><td>*0ET*.*.*</td><td>*</td></tr>
</table>

Customer states:

- The electric drive system warning lamp lights up in the dash panel insert.

and/or

- The warning lamp for an active warning lights up in the instrument cluster.

and/or

- Various messages about the electric drive system are displayed in the instrument cluster.

Workshop findings:

- One or more of the customer statements can be reproduced.

The following event memory entry (passive/intermittent or active/static) is logged in the electric drive control unit (diagnostic address 0051):

- **P0A2B00** Drive Motor "A" Temperature Sensor Circuit Range/Performance
  - Symptom: 41505

Technical Background

Software issue

Production Solution

Not applicable.

Service

This bulletin replaces PSS 2081343, *93 PSS Q4 e-tron - Electrical drive system warning lamp DTC P0A2B00 (41505)*.

Note before workshop visit:

- The service technicians should check that a combined software update TSB is available.
- The combined software update is now available for some of the affected vehicles. Before asking the customer to bring the vehicle into the workshop for repairs, please check whether a combined software update TSB is already shown for this vehicle in ElsaPro. You can also find this information in the central service info 2082956, *00 Service info: central overview of combined software update for MEB - according to UNECE - ID.S 5.4.3/ID.S 5.6.3*. If a combined software update TPI is not displayed, the combined software update is still being prepared, and the repair should still be postponed. The planned release schedule can also be found in the central service info 2082956.

Combined software update:

The combined software update is now available for some of the affected vehicles.

This complaint is solved in **VR target state ID S 5.6.3**. Please check the column **VR target state ID S 5.6.3** in the central service info **2082956**.

Here you can find information on whether the measure is already available via a combined software update TSB or whether the measure will be made available later.

Please run the combined software update if available. Proceed according to the combined software update TSB which is specified for this vehicle in the central service information **2082956**.

Warranty

The TSB number must always be noted in the “HST number” field in SAGA for ease of processing.

Billing is performed via the complaint related TSB. The service number and damage code from this complaint-related TSB must be stated when billing.

The repair operations for the combined software update can be found in the central service information 2082956.

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.

Service Number:	9350		
Damage Code:	0040		
Labor Operations:	Please refer to central service information 2082956	Work for a combined software update	Please refer to central service information 2082956
Claim Comment:	As per TSB 2083309/1		

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2083309**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.