Service Bulletin

Bulletin No.: PIP6141
Date: October, 2026

PRELIMINARY INFORMATION

Subject: 8T45 or VT40 with SES Light and DTC P07E5 / P073E After OTA Update

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2025		All	All	All	All
GMC	Terrain	2025		All	All	All	All

Involved Region or Country	U.S. and Canada
Condition	Some Chevrolet and GMC vehicles equipped with the 8T45 MGH or VT40 MRQ automatic transmission may experience: an SES light with DTC P07E5 and/or P073E (unable to engage drive and/or reverse) after an Over The Air update.
Cause	Issue may occur due to a software interaction after an OTA update.

Correction

Clear codes and shutdown vehicle for 10 minutes. After 10 minutes, restart vehicle and the issue should be resolved.

Note: There is no need to replace the TCM for this issue.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8481178*	Clear DTCs and power cycle following OTA	.3 Hr.
	*This is a unique Labor Operation for Bulletin use only.	

Version	1
Modified	10/28/2026 - Created on

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION

Copyright 2026 General Motors. All Rights Reserved.