Connection offline

Reporting obligation

Transaction No.: **2078729/3**

93 Reporting obligation pre repair: e-tron GT red electrical sys. warning lamp, vehicle does not start - P0DAC00 in 008C

Release date: Oct 1, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
RS e-tron GT	2022 – 2026	All	Not applicable
e-tron GT	2022 – 2024		
S e-tron GT	2025 – 2026		

REVISION HISTORY		
Revision	**Date**	**Purpose**
3	-	Revised title (Updated description) Revised *Condition* (Updated customer statement)
2	06/30/2026	Revised *Service* (Updated steps) Revised *Condition* (Updated workshop findings.)
1	08/19/2025	Initial publication

Customer states:

- The vehicle cannot be started.
- The red electrical system warning lamp lights up in the instrument cluster.

Workshop findings:

- The complaint can be reproduced.

The following DTC is logged (**static/intermittent**) in the control unit for hybrid battery management (diagnostic address 008C):

- **P0DAC00** Hybrid/EV battery Cell Balancing Circuit “A”

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

Verify the condition.

With the battery fully charged (if possible) read out all measured values for the high-voltage battery (diagnostic address 008C) and then upload the log to GFF paperless.

If the vehicle is within the New Vehicle Limited Warranty, contact a TAC (Technical Assistance Center) consultant before proceeding. Please attach the DTC and diagnostic log to the TAC ticket/TAC Web Ticket.

If you do not receive a reply from the TAC within two hours, perform the necessary repairs yourself.

We reserve the right to only pay out for warranty claims after thorough checks if a reporting obligation is not observed. We apologize for any inconvenience caused if delays in processing occur as a result.

Complaints already covered by a TSB in (ELSA) are exempt from this reporting obligation.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2078729**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.