Connection offline

Technical Service Bulletin Transaction No.: **2080446/4**

01 Engine control unit, fuel rail pressure sensor P01C400 (symptom 46312) 4-cyl. 2.0 TFSI

Release date: Oct 15, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment			
A5, Q5, and Q5 Sportback	2025	All	4 cyl. 2.0l TFSI			
			00A5 - Front sensor for driver assistance systems			
			Software part number	**Software version**	**Hardware part number**	**Hardware version**
			*	0295	*	*
			*	0250	*	*

REVISION HISTORY		
Revision	**Date**	**Purpose**
4	-	Revised *Service* (Updated KD2 reference) Revised *Warranty* (Updated labor operations)
3	06/25/2026	Revised *Condition* (updated workshop findings) Revised header (added model year)
2	01/28/2026	Revised warranty table (Added labor operation)

Customer states:

- The exhaust emissions warning lamp lights up in the instrument cluster.

Workshop findings:

- The following DTC and symptom code is logged in *the control module name* -J623-, (address word 0001)
  - **P01C400** “Fuel Rail Pressure Sensor 1 Range/Performance” with symptom **46312**.

Technical Background

Software issue in the engine control unit.

Production Solution

Not applicable.

Service

This bulletin replaces PSS 2080114, *01 PSS Engine: Engine control module, fuel rail pressure sensor P01C400 (symptom 46314) 4 cyl. 2.0 TFSI.*

The complaint is solved with the target combined software version 03. 10.00/C {KD2}. This combined software package has already been rolled out. Please note that the KD package may have been superseded by a subsequent combined software update. All information about the current schedule and availability of the measure can be found in the central service information 2081477.

Warranty

Billing is performed via the complaint related TSB. The service number and damage code from this complaint-related TSB must be stated when billing.

The TSB number must always be noted in the “HST number” field in SAGA/2 for ease of processing.

If you are billing according to the warranty guidelines, please note the following accounting instructions:

Repair operations: please refer to central service information 2081477.

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	KD2S		
Labor Operations:	Please refer to central service information 2081477	Work for a combined software update	Please refer to central service information 2081477
Claim Comment:	As per TSB 2080446/4		

Please note the information on predecessors and items that are included and excluded in the repair operations as well as any associated tasks.

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The software must be updated on a control unit in this vehicle, or the software must be updated on several control units in this vehicle to ensure they function correctly in conjunction with the other control units in this vehicle. Please inform the customer about the software update in question and ask whether they or other third parties have modified the software (e.g. tuning or retrofitting involving modifications to the vehicle software).

Please inform the customer that this software update may neutralize previous modifications to the vehicle software performed by either the customer or other third parties.

If the customer declines the software update, please inform them that this could lead to issues or restrictions with the use of the vehicle or individual components.

Make a note to this effect on the order before it is signed by the customer. Include this information in the customer file.

All part and service references provided in this TSB (**2080446**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are

reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.