



Bulletin No.: PIP6040
Published date: 01/24/2025

Preliminary Information

PIP6040 Medium Duty Trucks Setting P2BAA

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet Silverado	MD 4500HD	2023	All	All 6.6L L5D	All
Chevrolet Silverado	MD 5500HD	2023	All	All 6.6L L5D	All
Chevrolet Silverado	MD 6500HD	2023	All	All 6.6L L5D	All

Involved Region or Country	North America
Concern:	The vehicle may have a concern with CEL (check engine lamp) on with a Warning Message = Service Emission System / Service Exhaust Fluid System.
Cause:	2023 medium duty trucks built with a 6.6L L5D engine may set a P2BAA Exhaust NOx Concentration High - Low Reductant Consumption.

Correction:

There is no need to replace any parts currently.

Engineering knows about the concern and is developing a calibration to address this concern.

When the calibration is released, this document will be updated to a service bulletin.

Version History

Version	1
Modified	01/24/2025 - Created on.

