

On-car analysis list from January 13th, 2025
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Cross Sport	24-25	All	All	MIL-on P0442	Customer states MIL-on, P0442 stored in ECM memory (leak must be from fuel cap area) (Untouched vehicles)
Electric	Tiguan	24	All	All	Seat Cover	Customer states the seat cover has discoloration (usually yellowing) stains (Untouched vehicles)
E-Mobility	ID.4	21-24	All	All	CMCe Faults	Customer states Electrical System Error Message, U04A1 [42304], U04A5 [42336], and/or U04A9 [42444] stored in DA:008C (No other relevant DTCs stored in DA:008C)
	ID.4	23-24	All	All	No Start (Tow In)	Customer states vehicle does not start; key not detected. No communication to J519 active. AW 19: U014000[2170894][2240526], B1248F3[1074443], U17B900[8398624] active DTC's (Untouched vehicles)