

On-car analysis list from January 21st, 2025
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Cross Sport	24-25	All	All	MIL-on P0442	Customer states MIL-on, P0442 stored in ECM memory (leak must be from fuel cap area) (Untouched vehicles)
	Atlas, Cross Sport	24-25	All	All	MIL-on P0068	Customer states MIL-on, P0068 stored in ECM memory
Electric	Tiguan	24	All	All	Seat Cover	Customer states the seat cover has discoloration (usually yellowing) stains (Untouched vehicles)
E-Mobility	ID.4	21-24	All	All	CMCe Faults	Customer states Electrical System Error Message, U04A1 [42304], U04A5 [42336], and/or U04A9 [42444] stored in DA:008C (No other relevant DTCs stored in DA:008C)
	ID.4	23-24	All	All	No Start (Tow In)	Customer states vehicle does not start; key not detected. No communication to J519 active. AW 19: U014000[2170894][2240526], B1248F3[1074443], U17B900[8398624] active DTC's (Untouched vehicles)
Body	Tiguan	24	All	All	Striker Plate	Customer states wind noise and or water ingress (Untouched vehicles)