

Check engine light on and FC P146264
stored in engine and fuel pump control units

Topic number	LI47.50-N-072080
Version	3
Function group	47.50 - Sender, feeler, sensors
Date	1/16/25
Validity	907 with engine M274 and fuel pump control unit FSCM Gen_5
Reason for change	Remedy modified

Complaint

Check engine light active and FC P146264 Temp. and pressure sensor B4/15 is stored in Engine control unit and Fuel pump control unit.

Cause

Software parameter in Fuel pump control unit.

Remedy

Please delete fault memory and do not replace any component parts. This LI will be updated once SW solution is available. A TIPS case is not required.

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms	
Power generation > Engine management > Indicator lamp > Engine diagnosis > lit	
Control unit/fault code	
Control unit	Fault text
N118/9 - Control unit 'Fuel pump' (FSCU) (FSCM_GEN5)	P146264 - The sensor 'Low fuel pressure and fuel temperature' has a malfunction. There is an implausible signal.

XENTRY Tips

N3/34 - Motor electronics 'MED40' for combustion engine 'M274' (ME) (MED40)	P146264 - The sensor 'Low fuel pressure and fuel temperature' has a malfunction. There is an implausible signal.
---	--

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note