

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title Long Range PHEV ERAD Sound Information		Ref. No. TJ 36166.3.0	
Issuer (Dept.) Technical Service		Issue Date 3/21/24	Status Date 4/16/24
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 4632	
Function Description Electrical rear axis drive		Page Page 1 of 2	

Attachment

File Name	File Size
ERAD 1 TJ 36166.wav	2.9993 MB
ERAD 2 TJ 36166.wav	6.9368 MB
ERAD 3 TJ 36166.wav	2.3109 MB

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* Adding vehicle types.

If a customer is concerned with noise from the ERAD, please follow the instructions under “Service”.

PHEV = Plug-In Hybrid Electric Vehicle

ERAD = Electric Rear Axle Drive

CSC Customer Symptom Codes

Code	Description
8N	Driving/Unusual noise/Unsure when/at all times
F2	Driving/Unusual noise/During acceleration
ZE	Idling/Unusual noise
D2	Front/rear axle/Unusual noise

DTC Diagnostic Trouble Codes

Technical Journal 36166.3.0

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224	H6	BH6PHEV					2022-9999		-	202147-999952
225	H6	BH6PHEV					2022-9999		-	202147-999952
238	H6	BH6PHEV					2022-9999		-	202147-999952
246	H6	BH6PHEV					2022-9999		-	202147-999952
256	H6	BH6PHEV					2022-9999		-	202147-999952

SERVICE:

A slight whining sound noticed during electric drive is to be considered normal.

Listen to the attached sound files as a reference. (ERAD 1,2 and 3) These are considered to be a normal electrical motor sound.

(Use of a headset or earphones is recommended. The sound files are recorded from the front seat at the head position.)

***In cases where the sound level is borderline to the attached files start by following TJ 36841.**

If you are unsure the noise is normal, please submit a TIE Support-Needed vehicle report and include a recording of the noise.

(Record the sound from the front seat at the head position with a mobile device also showing the dashboard in which speed and drive mode you are driving.)

Warranty claim info:

No warranty claim is accepted for a job described in this Technical Journal since it is to be used as a guidance.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub-concern area "Support Needed", use function group 4632.

This TJ includes three audio files.