



SSM 53455 2022 F-Super Duty - "Trailer Brake System Fault" With DTC U0131

Some 2022 F-Super Duty vehicles may exhibit a "Trailer Brake System Fault" message with diagnostic trouble code (DTC) U0131 stored in the trailer module (TRM). This may be due to the TRM configuration after a previous software update. To correct the condition, download and run the TRM - Trailer Module (TRM) Configuration application using the latest software version of the Ford Diagnosis and Repair (FDRS) diagnostic scan tool. For claiming, use causal part 19H332 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.