



**Bulletin No.:** PIT6351  
**Published date:** 03/10/2025

## Preliminary Information

### PIT6351 Service A/C System Message P0071

#### Models

| Brand:    | Model:     | Model Years: | VIN: |     | Engine: | Transmissions: |
|-----------|------------|--------------|------|-----|---------|----------------|
|           |            |              | from | to  |         |                |
| Cadillac  | LYRIQ      | 2024 - 2025  | All  | All | All     | All            |
| Cadillac  | OPTIQ      | 2025         | All  | All | All     | All            |
| Chevrolet | Blazer EV  | 2024 - 2025  | All  | All | All     | All            |
| Chevrolet | Equinox EV | 2024 - 2025  | All  | All | All     | All            |

|                            |                                          |
|----------------------------|------------------------------------------|
| Involved Region or Country | North America                            |
| Additional Options (RPO)   |                                          |
| Condition                  | Service AC system message. P0071 is set. |
| Cause                      | Engineering is investigating.            |

**Correction:**  
Scan vehicle for codes.  
If P0071 is found follow circuit system testing in SI to test circuits.  
If no circuit faults are found do not replace any parts.  
Clear codes and advise customer that engineering is currently working on a design improvement.

#### Version History

|          |                     |
|----------|---------------------|
| Version  | 1                   |
| Modified | Created on- 3/10/25 |