

Audi On-car analysis list from March, 03 2025**Please contact Audi Helpline before attempting repair****As of 6/7/2024 worksheets will no longer be used as a standard practice. Worksheets will only be required if listed in the topic details.**

	Models	MY	Engine	Trans	Topic	Topic details
	Q5	2022-2025	DPVA	Any	Leaking timing chain cover Gasket	Before performing work on the vehicle proceed as follows: 1.Please take clear photos, and clear video of the active leak. 2.Contact TAC for further instruction.
	Q5	2022-2025	2.0T	Any	Oil leak from oil filter	Clear photos showing oil leak and oil filter o-ring Contact TAC with photos attached in case
	A4, A5, Q5, Q7	2022-2025	2.0L engines only	any	ECM DTC P060600 "ECM/PCM Processor"	Before performing work on the vehicle proceed as follows: 1.If fault is present, please try and clear fault. If the fault is cleared, please test drive 20 miles and see if you can reproduce the fault. 2.Contact TAC for further instruction.
	A4, A5, Q5, Q7	2022-2025	2.0L engines only	Any	Engine oil pressure switch	MIL on with DTC • P055F00 Engine Oil Pressure Out of Range ° and/or • P055C00 Engine Oil Pressure Sensor/Switch "B" Low Contact TAC for direction
	Q7	2022-2025	any	Any	Airbag light on for DTC B12251B	Before performing work on the vehicle proceed as follows: 1. Contact TAC for further instruction.
	A4, A5, Q5, Q7	2024-2025	any	Any	Noise from engine belt tensioner	Before performing work on the vehicle proceed as follows: 1.Verify the belt tensioner is making noise. 2.Please refer to TSB 2070568 and use PICO tool to take basic acoustic measurements of engine area. The tool needs to be placed in engine bay area no specific location. 3.Contact TAC. Please attach PICO readings to ticket.
	Q7, Q8	2024-2025	any	Any	Steering column switch dislocated	Customer states steering column switch is dislocated from the column. Contact TAC with photos attached for further direction.
	A3, S3, RS3	2022-2025	any	Any	Sunroof shade binds	PQA onsite needed Inquire if the vehicle is able to be left at dealer and an onsite inspection scheduled If so, create a TAC case and wait for instruction