

Vehicle-specific service

Topic	19 PSS Engine: Radiator blind - fault. Maximum speed limit to 10 mph A3 DTC's P05AF00, P05B200, P05A000, P05A300
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2073088/3
Level	EH
Status	Released for publishing
Release date	Feb 25, 2025

Vehicle data

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
8Y*	2022	A		*	*	*
8Y*	2023	A		*	*	*
8Y*	2024	A		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
WAU	*	GY	*	N	A	000000	999999		
WAU	*	GY	*	P	A	000000	999999		
WAU	*	GY	*	R	A	000000	999999		

Documents

Document name
master.xml



Connection offline

Vehicle-specific service

Transaction No.: **2073088/3**

19 PSS Engine: Radiator blind - fault. Maximum speed limit to 10 mph A3 DTC's
P05AF00, P05B200, P05A000, P05A300

Release date: Feb 25, 2025

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Service</i> (Adjusted solution date)
2	12/03/2024	Revised <i>Service</i> (Adjusted solution date) Revised <i>Warranty</i> (Updated Claim Types, Labor Operations)
1	04/05/2024	Initial Publication

Customer states:

There is a message in instrument cluster: "Radiator blind fault Maximum speed limited to 10 mph. Please contact workshop."

Workshop findings:

One or more of the following DTC's are stored in ECM, J623 (address word 0001):

- **P05AF00** – active radiator blind 2 sticks open – with symptom 28397.

and/or

- **P05B200** – active radiator blind 2 lost communication – with symptom 28405.

and/or

- **P05A000** – active radiator blind 1 sticks open – with symptom 28396.

and/or

- **P05A300** – active radiator blind 1 lost communication – with symptom 28408.

Technical Background

Engine control unit issue

- In rare cases the following message may be shown in the cluster Radiator blind fault Maximum speed limited to 10 mph. please contact workshop.
- The maximum speed limit should specify 100 mph rather than 10 mph.
 - Please refer to TSB 2074984 regarding a display of 10 mph rather than 100 mph.
 - In almost all cases the complaint is fixed after turning the ignition off and on again.
- Be aware that the complaint may reappear at speeds greater than 100 mph.

Production Solution

Not applicable.

Service

1. Explain to the customer that a solution is not expected to be available before the 2nd quarter of 2025 (subject to change), no increased wear or other negative effects on the vehicle are to be expected, and that no repairs are necessary at this point.
2. **Do not replace any components** for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

Warranty

Claim Type:	• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1935		
Damage Code:	0016		
Labor Operations:	GFF	0150 0010	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2073088/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2073088**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.