

9100508

03/28/2025

MY 19-24 DD 19-24 DJ 19-24 DP 19-24 D2

GPOP - Issue Review System

Part Number: 68458603A\$

Part Description: 6 CONTROL UNIT, Diesel Exhaust

Issue Description: Customer complaints with malfunction light illuminated on 2019 thru 2024 MY DJ / D2 / DD / DP vehicles with 6.7L (ETL / ETM / ETN) built on or before October 15, 2024 and exhibiting DTCs P21C4-00 (Reductant Line Heater Relay Control Circuit High) and / or U11C1-00 (Reductant Control Module received implausible Data from ECM / PCM). These DTCs will occur after installation of service DCU 68458603AB. Do not replace parts until after the TSB 25-008-24 is performed. If the DTC(s) continue to set, then follow the Service Diagnostics for the applicable DTC.