

GPOP - Issue Review System

Part Number: 68583903A\$

Part Description: Body control module

Issue Description: Customer may experience the compass on Radio "ETM/LTM" and IPC to display "--". Technician will also experience this as well as BCM DTC U147C-00 "Implausible data received from ETM" as active until the customer/technician drives the vehicle around Steps to revive:
- 1.Drive vehicle around until the compass direction appears in IPC and ETM/LTM. 2.also a reset to the radio may recover the issue until the next sleep cycle.