

On-car analysis list from March 31st, 2025
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Cross Sport	24-25	All	All	MIL-on P0442	Customer states MIL-on, P0442 stored in ECM memory (leak must be from fuel cap area) (Untouched vehicles)
	Atlas, Cross Sport	24-25	All	All	Oil Leak	Oil leak from Cylinder Head Cover (Untouched vehicles) (MY24 after engine serial DRK 154894)
	Atlas, Cross Sport	25	All	All	MIL-on P0087	Customer states MIL-on, P0087 Stored in ECM memory (Untouched vehicles)
Electric	Atlas, Cross Sport	24 - 25	All	All	Key Lock/Unlock functions inoperative	Customer states key functions (FOB or KESSY) for lock and/or unlock are inoperative
Body	Tiguan	24	All	All	Striker Plate	Customer states wind noise and or water ingress (Untouched vehicles)
	Atlas, Cross Sport	24-25	All	All	Seat Rattle	Customer states middle row seat rattles (Untouched vehicles) (VIN AFTER: Atlas - RC546450 ; Cross Sport - RC224823)
Chassis	Atlas, Cross Sport	24	All	All	Driveshaft Vibration	Customer states vibration from front of the vehicle at highway speeds (Untouched vehicles)
	Atlas, Cross Sport	24	All	All	Anti-Roll Bar Coupling Link Noise	Customer states there is a noise from the front of the vehicle (Untouched vehicles)
	Atlas, Cross Sport	24-25	All	All	CV Boot Leaking	Customer states there is a leak from the front of the vehicle (Untouched vehicles)
	Tiguan	22-24	All	All	Brake Caliper Noise	Customer states there is a noise from the front of the vehicle (Untouched vehicles)