

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title DTC ASDM-U230055 after software download		Ref. No. TJ 37292.1.0	
Issuer (Dept.) Technical Service		Issue Date 3/3/25	Status Date 3/14/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA		Function Group 3872
Function Description Collision avoidance		Page Page 1 of 1	

DESCRIPTION:

If the DTC ASDM-U230055 is detected after the software is downloaded, please follow the advice under "Service."

ASDM = Active Safety Domain Master

DTC = Diagnostic Trouble Code

CSC Customer Symptom Codes

Code	Description
2V	Technician information/Software/Vehicle communication/Not for warranty use

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
ASDM	U230055	Intermittent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
416							2024-9999		-	202336-999952

SERVICE:

No action is required for the DTC, as there is no associated customer symptom. It will be cleared automatically after two driving cycles.

Warranty claim info:

No warranty claim is accepted for this TJ.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3872.