



Bulletin No.: PIP6059
Published date: 04/17/2025

Preliminary Information

PIP6059 MIL / SES Light On DTC P04FB

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Equinox	2025	All	All 1.5 LSD	All
GM	Terrain	2025	All	All 1.5 LSD	All

Involved Region or Country	North America
Condition	Customers may have a concern of MIL with P04FB stored.
Cause	Engineering is currently working on a design improvement

Correction:
Engineering is currently working on a design improvement.

Please refrain from replacing parts.

Clear the code as needed and return the vehicle to the customer.

Customer Information

Please communicate to the customer this will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

Version History

Version	1
Modified	04/17/2025 - Created on.