



SSM 53668 2025 Expedition/Navigator - DTCs B150D:55 And/Or B150C:55 Stored In The ACM

Some 2025 Expedition/Navigator vehicles may exhibit diagnostic trouble codes (DTCs) B150D:55 and/or B150C:55 stored in the audio control module (ACM) when a diagnostic self-test is performed. If no other symptoms, DTCs, or issues are identified, no further action is required. Replacement and/or reprogramming of the ACM will not resolve this condition.