



STAR ONLINE PUBLICATION



Case Number: S2521000002

Release Date: June 2025

Symptom/Vehicle Issue: Malfunction Indicator Lamp (MIL) Illuminated. Diagnostic Trouble Code (DTC) P1DF3 – ECU Not Initialized, Set.

Discussion: Some customers may experience a MIL illumination. Upon further investigation, the technician may find DTC P1DF3 setting in the Transmission Control Module (TCM).

If you are working on a vehicle with the above condition, please follow normal published diagnostics and verify there are no wiring or harness connection issues. If no wiring or connection issues are found, do not replace any parts at this time. This concern is currently under investigation for a potential software update.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.