

Field campaign

Topic	Software Update BJB and HV ECUs Continental GT/GTC/Flying Spur 25MY (SC25/10)
Market area	Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)
Brand	Bentley
Transaction No.	2077696/6
Campaign number	ED40
Note	
Type	
US code	

Vehicle data

25MY Continental GT/GTC/Flying Spur

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
Z23*	2025	E		*	*	*
Z24*	2025	E		*	*	*
Z32*	2025	E		*	*	*

Documents

Document name
master.xml
ed40vinlist.pdf

.....

Notes



Technical background

Software updates must be applied to update the vehicles Baseline Integration Level (BiL).

The software update corrects the following Diagnostic trouble codes (DTCs):

- P060100: High Voltage Battery (Address 008C) Internal Control Module Memory Checksum Error
- P057F00: Battery "A" State of Charge Performance, B11B300 Igniter for high voltage battery interrupt
- P0A0B00: High Voltage System Interlock Circuit Performance (HVIL).

CAUTION

If Campaign ED18 is marked as an outstanding Campaign in ElsaPro, it must be completed before starting this update

Remedy

The instructions within the 'Work' section **must** be conducted to completion.

Customer notification

Please ensure all applicable instructions are conducted at the nearest opportunity.

Warranty

SVM Update Time

Claim type: 790 or 710

Service number: ED40

Damage code: 0066

Criteria:01

Labour Operation Code: 01 51 00 00

Time: As per ODIS log (Must not exceed 200TU)

Additional Time Allowance

A 100TU allowance may be claimed only if a SVM update fails to complete successfully. This is intended to cover additional diagnostic or recovery work directly resulting from the failed update. It must not be used for unrelated delays or issues.

ODIS logs must be attached to a DISS ticket for evidence of failure. Claims without valid documentation will be rejected. Warranty Adjudicators will review associated ODIS logs and DISS queries to determine actual software update time.

Parts

Not Applicable

Parts supply

Not Applicable

Parts despatch control

Not Applicable

Repair instructions



Technical background

Software updates must be applied to update the vehicles Baseline Integration Level (BiL).

The software update corrects the following Diagnostic trouble codes (DTCs):

- P060100: High Voltage Battery (Address 008C) Internal Control Module Memory Checksum Error

- P057F00: Battery "A" State of Charge Performance, B11B300 Igniter for high voltage battery interrupt
- P0A0B00: High Voltage System Interlock Circuit Performance (HVIL).

CAUTION

If Campaign ED18 is marked as an outstanding Campaign in ElsaPro, it must be completed before starting this update

Check

Check if the vehicle is already listed as repaired in "Repair history" (in ElsaPro).

Please also refer to the "Identification" section and check if a paint identification mark is evident in the vehicle.

If the vehicle is not shown in ElsaPro as repaired, and the identification mark is not present, please conduct the instructions within the 'Work' section to completion

Parts

Not Applicable

Work

CAUTION

The Bentley ODIS-S Brand Version **MUST** be at least 2.35.2 (or higher).

CAUTION

Before conducting the onward instructions, the operative **MUST** recheck the communication method in ODIS and ensure that DoIP is selected before proceeding. Within ODIS-S, perform the following:

- On the right hand side, select the "Admin" tile (Within 'Operating modes')
- Select "GFF sequence" (Within 'General information' section)
- Under the "Selection of Communication path" drop-down menu, select "Only permit DoIP communication".

CAUTION

DO NOT, UNDER ANY CIRCUMSTANCES, ATTEMPT TO CONDUCT THE SOFTWARE UPDATE VIA THE CAN NETWORK. ONLY DoIP SHOULD BE USED WHEN PERFORMING THE SVM UPDATE.

CAUTION

You **MUST ONLY** use the Diagnosis Interface VAS 6154 (WiFi Diagnostic Tool) in USB OPERATION or the CABLE-CONNECTED VAS 5055 for the reprogramming (updating) of the control units.

- If neither of these units are available, the VAS 5054 (A) may be used in USB MODE.
- **DO NOT** under any circumstances use a Bluetooth connection to conduct the reprogramming (updating) of any control units.

Battery Charger

CAUTION

ONLY Chargers that meet the approved specification on the Mandatory Equipment List (available on the Bentley Hub) **MUST** be used.

- The charger must be set to a mode where a **MINIMUM** of 90a is supplied to the battery during the process. Typically, this is known as 'Power Supply Mode' or 'DIAG+ Mode'.
- A voltage of exactly 14.8v must be set and maintained throughout the process.
- Please refer to the manual to ensure that these requirements are met before beginning any SVM update

Preparation Before Update

WARNING


Hybrid Vehicles use a High Voltage System and therefore **MUST ONLY** be worked on by suitable personnel

CAUTION

During the update, switch off all unnecessary consumers. For example, ventilation, seat heaters, interior illumination, exterior lights ect.

Conduct a full guided fault find of the vehicle.

If a 'Check Installation List' pop-up appears, select 'close' (see below image)



Referring to TPI 2075920, address any unknown faults **BEFORE** conducting any of the below updates.

Ensure that the correct battery charger is connected to the vehicle. – Refer to the “Battery Charger” Section above.

Obtaining flash files for ODIS-S

NOTICE

The Bentley ODIS-S Brand Version 2.35.2 does not require Hotfix. Only loading of the local flash files.


Visit <https://bentley.atheer.io/> and log in with the following case-sensitive account details.

- Username: bilupdate
- Password: Bentley123!

NOTICE

If you are already logged into your retailer account, you will need to logout first. To do this, click on your account initials (bottom left corner) and click “Sign Out”.

After logging in, using the navigation bar on the left hand side, click on the 'conversations' tab



Next, click the conversation named “ED40 Campaign”.

NOTICE

You **MUST NOT** leave the conversation, remove users from the conversation, delete the conversation or alter the conversation in any way. The **ONLY** action you are permitted to perform is download the applicable file required for this campaign.

In this conversation, you will find a file named “ED40_Local_Flash_Files”.

Left click the file name and download the folder.

After left-clicking the files to download them, the download may take circa 5-10 minutes, do not interrupt this process. You may need to wait a short period (internet speed dependent) for the files to download.

During/before the download commences, there may be a warning about a "pop-up" being blocked which will prevent the file from downloading, ensure to select option "Allow Pop-Ups from this website" to download the file. Wording may differ depending on web browser.

Locate the download file and extract it. To do this, right click the file, click "7 zip" and then "Extract here"

After successfully downloading the file, please logout of the account.

Downloading Flash Files for ODIS-S

From the content within the 'ED40_Local_Flash_Files' download, copy the content of the folder into your root c:/temp drive on your ODIS device.

- FL_4M0915249AN_0201_UPD0004T0005_V001_S.odx
- FL_4M0915249AM_0207_ABJB7A60590M1_V001_S.odx
- FL_4M0915231AH_0204_XHX15EV0421M6_V001_S.odx

High Voltage Shutdown

 WARNING
De-energise the high-voltage system via ODIS-S. Refer to ElsaPro, Repair Group 93 – "De-energising high-voltage system" to do so.

1. After de-energisation, Refer to ElsaPro Repair Group 70 'Boot carpet – To remove and fit'. Remove the boot floor and gain access to the earth cable from the 12v battery negative and the body in white (This access will be required later in the test plan).

2. Navigate to 'Special functions' and select 'SVM – Pre 372BIL5201 Hotfix Routines', then 'Perform test'.

3. Switch to 'DoIP' when prompted.

4a. For Continental Flying Spur Vehicles Select '1) BMC/BJB 204/207 Update Repair' and follow the on-screen instructions.

4b. For Continental GT/GTC Vehicles Select '8) BMC/BJB 204/207 Update Repair' and follow the on-screen instructions.

- When the tester attempts to flash '008C - Battery regulation control module' you may receive a message informing you that the pre-conditions have not been met. Select 'done/continue'.
- On the following screen (shown below) select option 2 to attempt to flash the ECU – this should allow the '008C - Battery regulation control module' to flash successfully.

 NOTICE
If the flash fails, perform the below actions.

1. Exit the test.

2. Allow the car to sleep for 5 minutes.

a. Turn off the ignition.

- b. Remove all equipment from the car (Diagnostic tester/dongle, battery charger, keys).
- c. Close all doors, windows, bonnet and boot lid.
- d. Lock the vehicle to perform a CAN-BUS sleep (wait 5 minutes).

3. Clear DTCs from '008C - Battery regulation control module'.

3a. To do this, right click on control unit 008C, click Guided Functions and then click 'Clear Fault Memory'.

4. Return to 'Special functions' and run the test plan 'SVM – Pre 372BIL5201 Hotfix Routines'.

5. Within this test plan, select option 5 (008C BCM - Restore Communications with BJB) and run until completion.

6. Once the test has been completed, right click on control unit 008C and select guided functions. Then, read ECU Identification and ensure that the 06D0 (Battery Junction Box) appears as a subsystem within the read identification test plan.

7. Continue to the next SVM update.

SVM Code Input

 WARNING
Re-energise the high-voltage system via ODIS-S. Refer to ElsaPro, Repair Group 93 – “Re-energising high-voltage system” to do so.

1. After re-energising the High Voltage System, navigate to the “Special Functions” tab in ODIS-S.

2. Navigate to 'SVM – Code Input' and enter the SVM Code.

a. If the vehicle is any variant of a Continental GT or GTC, enter the SVM Code: “372ED40COM01”.

b. If the vehicle is any variant of a Continental Flying Spur, enter the SVM Code: “373ED40COM01”.

3. On the next screen, ensure that the SVM code displayed is correct.

4. You will be shown the communication type. **This MUST be set to “DoIP”.**

a. If “DoIP” is not selected, select option 3 until the communication type is set to “DoIP”.

5. After ensuring DoIP is selected, and a suitable battery charger is connected, select Option 1 – “Yes”.

a. From here, all control modules will be interrogated and the SVM action will take place.

6. Ensure that the diagnostic device remains connected for the duration of the update.

7. Follow all on-screen prompts until the program ends.

a. If you have a prompt stating there is no communication established with 00CC, select done/continue.

8. Follow the on-screen instructions to completion.

9. If you are presented with this screen (Fig 3) at the end of the update, the update was successful. Please continue to step 11.




Fig 3

10. If you encounter any errors during the update, please raise a FULL TECHNICAL DISS query.

- a. Customer Statement: "ED40 Support"
- b. Workshop Findings: Give a summary of the error encountered and ensure that the latest Guided Fault Finding log is submitted online.

11. After successful completion of the update, perform the following.

- a. Turn off the ignition.
- b. Remove all equipment from the car (Diagnostic tester/dongle, battery charger, keys).
- c. Close all doors, windows, bonnet and boot lid.
- d. Lock the vehicle to perform a CAN-BUS sleep (wait 15 minutes).


12. After 15 minutes, unlock and open the driver's door. Turn on the ignition, re-connect the battery charger and diagnostic dongle.

13. Re-run guided fault finding and clear DTCs. If any faults are present, refer to TPI 2075920. If any other faults are present, please raise a full DISS query with a full GFF log uploaded online stating the error encountered.

Identification

Once the applicable action has been conducted, the operative must submit a warranty claim as this will show the service campaign action as complete within Elsa Pro "Repair history".

You must also add a yellow paint mark to the underside of the Fusebox cover as per the picture below.



 [Repair instructions](#)  [Notes](#)

SCBCF13SXSC022378	SCBDF33S1SC022432	SCBDF33S2SC022469
SCBCG13S3SC022381	SCBDF33S2SC022441	SCBDF33S3SC022478
SCBCF13S8SC022380	SCBDF33SXSC022428	SCBBR6ZG1SC022496
SCBCF13S9SC022405	SCBDR4ZG3SC022447	SCBBR6ZG4SC022427
SCBCG13S7SC022397	SCBBR6ZG1SC022384	SCBBR6ZG5SC022436
SCBCJ13S2SC022390	SCBBR6ZG3SC022466	SCBBR6ZG8SC022396
SCBCR2ZG4SC022408	SCBBR6ZG4SC022377	SCBBR6ZG9SC022438
SCBCR2ZG6SC022376	SCBBR6ZG7SC022485	SCBBR6ZG9SC022472
SCBDF33S3SC022383	SCBBR6ZGXSC022416	SCBBG53S9SC022470
SCBDF33S4SC022375	SCBBR53S1SC022425	SCBBF53S1SC022420
SCBDF33S4SC022389	SCBBR53S4SC022404	SCBBF5ZG9SC022457
SCBDF33SXSC022395	SCBBR53S5SC022394	SCBBF5ZGXSC022483
SCBDR4ZG2SC022391	SCBBG53SXSC022445	SCBCF13S1SC022477
SCBDR4ZG7SC022385	SCBBF53S0SC022392	SCBCF13S1SC022527
SCBBR6ZG2SC022409	SCBCF13S0SC022468	SCBCF13S1SC022530
SCBBR6ZG9SC022388	SCBCF13S1SC022480	SCBCF13S5SC022501
SCBCF13S2SC022424	SCBCG13S4SC022499	SCBCF13S5SC022515
SCBCF13S6SC022393	SCBCG13S8SC022490	SCBCF13S9SC022467
SCBCF13S9SC022419	SCBCG13S9SC022434	SCBCR2ZG2SC022505
SCBCR2ZG0SC022406	SCBCR2ZG0SC022387	SCBDF33S4SC022473
SCBCR2ZG3SC022402	SCBCR2ZG8SC022458	SCBDF33S7SC022497
SCBDR4ZG5SC022403	SCBCR2ZG8SC022475	SCBDF33S8SC022525
SCBBG53S6SC022412	SCBCR2ZG9SC022484	SCBDJ3ZG9SC022518
SCBCF13S0SC022454	SCBDF33S7SC022452	SCBDR4ZG4SC022456
SCBCF13S2SC022410	SCBDF33S8SC022489	SCBDR4ZG6SC022426
SCBCF13S5SC022417	SCBDR4ZG3SC022500	SCBCF13S0SC022521
SCBCF13S5SC022465	SCBDR4ZG4SC022411	SCBDF33S0SC022423
SCBCF13S7SC022421	SCBDR4ZG5SC022482	SCBBF53S6SC022476
SCBCF13S8SC022461	SCBDR4ZGXSC022459	SCBBG53S6SC022474
SCBCF13SXSC022414	SCBDR4ZGXSC022462	SCBBG53S9SC022498
SCBCG13S4SC022437	SCBCF13S1SC022463	SCBBR6ZG1SC022448

SCBBR6ZG1SC022479	SCBCF13S0SC022597	SCBDF3ZG3SC022595
SCBBR6ZG4SC022511	SCBCF13S1SC022544	SCBCF13S0SC022633
SCBBR6ZG5SC022453	SCBCF13S6SC022586	SCBCF13S9SC022629
SCBBR6ZG7SC022504	SCBCF13S9SC022596	SCBCF13SXSC022610
SCBBR6ZGXSC022531	SCBCF1ZG7SC022602	SCBCR2ZG6SC022541
SCBCF13S1SC022494	SCBCR13S9SC022508	SCBCR2ZG6SC022619
SCBCF13S1SC022561	SCBCR2ZG0SC022566	SCBDR4ZG2SC022617
SCBCF13S9SC022503	SCBCR2ZG1SC022575	SCBDR4ZG3SC022612
SCBCF13SXSC022557	SCBCR2ZG2SC022519	SCBDR4ZG7SC022502
SCBCF1ZG0SC022442	SCBCR2ZG2SC022570	SCBCF13S7SC022578
SCBCJ13S6SC022506	SCBCR2ZG3SC022593	SCBBF53S0SC022537
SCBCR13S4SC022545	SCBCR2ZG7SC022550	SCBBF53S1SC022529
SCBCR2ZG3SC022495	SCBDF33S9SC022582	SCBBR6ZG5SC022520
SCBCR2ZG4SC022568	SCBDF33SXSC022493	SCBBR6ZG5SC022551
SCBDF33S3SC022559	SCBDR4ZG5SC022577	SCBBR6ZG7SC022440
SCBDF33S5SC022546	SCBCF13S0SC022471	SCBBF53SXSC022626
SCBDF33S7SC022516	SCBCF13S4SC022487	SCBBF5ZG4SC022611
SCBDF33S8SC022539	SCBBF53S3SC022547	SCBBG53S0SC022552
SCBDR4ZG5SC022532	SCBBF5ZG2SC022588	SCBBG53S5SC022613
SCBCF13S2SC022536	SCBBG53S2SC022584	SCBBR53S3SC022569
SCBBF53S3SC022564	SCBBG53S3SC022576	SCBBR6ZG2SC022524
SCBBF53S5SC022386	SCBBG53S4SC022571	SCBBR6ZG2SC022605
SCBBF5ZG9SC022488	SCBBR53S0SC022481	SCBBR6ZG3SC022631
SCBBG53S3SC022433	SCBBR6ZG8SC022558	SCBBR6ZG5SC022601
SCBBG53S6SC022507	SCBBR6ZGXSC022464	SCBBR6ZG9SC022620
SCBBG53S8SC022542	SCBBR6ZGXSC022562	SCBBR6ZG8SC022379
SCBBJ53S6SC022556	SCBCF13S9SC022548	SCBDF33S2SC022486
SCBBR6ZG0SC022540	SCBCF13SXSC022591	SCBCF13S7SC022614
SCBBR6ZG6SC022509	SCBCR2ZG0SC022616	SCBCF13S9SC022565
SCBBR6ZG9SC022455	SCBDF33S5SC022563	SCBCF1ZG9SC022634
SCBBR6ZGXSC022514	SCBDF33S6SC022555	SCBCG13S0SC022645

SCBCR2ZG4SC022523	SCBBR6ZG0SC022649	SCBBR6ZG6SC022638
SCBDF33S1SC022592	SCBBR6ZG1SC022644	SCBBF53S4SC022590
SCBDF33SXSC022512	SCBBR6ZG6SC022574	SCBCL13S0SC022687
SCBDR33S9SC022587	SCBBR6ZG8SC022429	SCBCR2ZG7SC022659
SCBDR33SXSC022632	SCBBR6ZGXSC022609	SCBDF33S8SC022606
SCBBR6ZG1SC022594	SCBBF5ZG0SC022685	SCBCF13S0SC022700
SCBBG53S2SC022603	SCBCR2ZG5SC022689	SCBCF13S1SC022673
SCBCJ13S9SC022435	SCBDF3ZG8SC022639	SCBCL13S2SC022691
SCBDG33S0SC022418	SCBDP4ZG7SC022683	SCBCL13S3SC022702
SCBCF13S3SC022660	SCBDR4ZG5SC022627	SCBCL13S4SC022756
SCBCF13S8SC022654	SCBCF13S4SC022604	SCBCR2ZG5SC022739
SCBCP2ZG3SC022678	SCBCF13SXSC022655	SCBCR2ZG7SC022709
SCBCR2ZG0SC022650	SCBCH13S4SC022712	SCBCR2ZG8SC022637
SCBCR2ZG1SC022625	SCBCL13S2SC022710	SCBDF33SXSC022686
SCBCR2ZG2SC022553	SCBCP2ZG9SC022698	SCBDL33S3SC022716
SCBCR2ZGXSC022641	SCBDL33S1SC022679	SCBDL33S4SC022675
SCBDF33S3SC022643	SCBDR4ZG5SC022658	SCBDP4ZG1SC022677
SCBDF33S4SC022635	SCBDR4ZG8SC022668	SCBDR4ZG1SC022656
SCBDF33S6SC022572	SCBCF13S2SC022648	SCBCF13S9SC022694
SCBDF33S9SC022534	SCBCR13S6SC022725	SCBBF53S0SC022554
SCBDR4ZG4SC022652	SCBBG53S0SC022535	SCBBG53S1SC022513
SCBDR4ZG7SC022600	SCBBL53S9SC022688	SCBBG53S0SC022728
SCBDR4ZG7SC022662	SCBBR6ZG4SC022640	SCBBG53S8SC022752
SCBCF13S5SC022451	SCBBF53S0SC022618	SCBBG53S9SC022646
SCBBF5ZG2SC022560	SCBBG53S6SC022460	SCBBG53SXSC022719
SCBBF53S2SC022653	SCBBG53S6SC022667	SCBBG53SXSC022736
SCBBF53S3SC022581	SCBBL53S3SC022721	SCBBP6ZG1SC022682
SCBBG53S1SC022642	SCBBL53S9SC022674	SCBBR53S4SC022693
SCBBG53S5SC022661	SCBBR53S6SC022663	SCBBR6ZG3SC022628
SCBBG53S8SC022492	SCBBR6ZG0SC022697	SCBBR6ZG4SC022671
SCBBG53S8SC022623	SCBBR6ZG5SC022422	SCBBR6ZG6SC022669

SCBBR6ZG9SC022701	SCBBG53S5SC022742	SCBCL13S0SC022835
SCBBR6ZGXSC022657	SCBBP6ZG1SC022763	SCBCL13S1SC022729
SCBBF53S8SC022690	SCBBR6ZG7SC022695	SCBCL13S1SC022794
SCBCF1ZG9SC022665	SCBBR53S9SC022740	SCBCL13S4SC022790
SCBCF13S0SC022759	SCBBR6ZG4SC022766	SCBCL13S7SC022735
SCBCF13S2SC022780	SCBCG13S4SC022583	SCBCL13SXSC022681
SCBCF13S4SC022778	SCBDG33S3SC022624	SCBCP2ZG9SC022684
SCBCF13SXSC022722	SCBCF13S7SC022743	SCBCR2ZG0SC022812
SCBCH13S0SC022772	SCBCL13S0SC022737	SCBCR2ZG8SC022816
SCBCL13S3SC022764	SCBCL13S1SC022813	SCBCR2ZGXSC022767
SCBCL13S8SC022727	SCBCL13S4SC022787	SCBCR2ZGXSC022798
SCBCL13S8SC022761	SCBCR13S8SC022807	SCBDF33S3SC022805
SCBCP2ZG0SC022749	SCBCR2ZG0SC022793	SCBDF33S8SC022797
SCBCR2ZG4SC022733	SCBDL33S5SC022751	SCBDF33SXSC022784
SCBCR2ZG7SC022774	SCBDL33S5SC022779	SCBDL33S3SC022814
SCBDF33S0SC022647	SCBDR33S1SC022776	SCBDL33S6SC022788
SCBDF33S0SC022714	SCBDR4ZG6SC022765	SCBDL33S6SC022791
SCBDF33S0SC022731	SCBCF13S6SC022720	SCBDL33S6SC022824
SCBDF33S0SC022762	SCBCF13S8SC022783	SCBDP4ZG1SC022758
SCBDF33S4SC022585	SCBBG53S0SC022549	SCBDP4ZG9SC022782
SCBDL33S0SC022771	SCBBG53S2SC022651	SCBCF13S3SC022741
SCBDR4ZG1SC022768	SCBBL53S7SC022804	SCBDF33S3SC022755
SCBDR4ZG3SC022528	SCBBP6ZG5SC022703	SCBBF53S1SC022580
SCBDR4ZG4SC022747	SCBBR6ZG2SC022748	SCBBF53S5SC022730
SCBCF13S1SC022785	SCBBR53S6SC022811	SCBBF53S9SC022777
SCBCF13S3SC022769	SCBCR2ZG1SC022608	SCBBG53S2SC022746
SCBCF13S6SC022443	SCBCF13S0SC022809	SCBBG53S4SC022599
SCBBG53S9SC022517	SCBCF13S0SC022826	SCBBL53S2SC022676
SCBBG53SXSC022526	SCBCF13S6SC022622	SCBBL53S9SC022786
SCBBF53S5SC022789	SCBCF13SXSC022803	SCBBP6ZG6SC022760
SCBBF53S9SC022715	SCBCG13S9SC022840	SCBBR6ZG0SC022795

SCBBR6ZG0SC022831	SCBBR6ZG2SC022801	SCBBR6ZG4SC022833
SCBBR6ZG8SC022723	SCBBR6ZG4SC022847	SCBBR6ZG9SC022827
SCBCF13S4SC022439	SCBBR6ZG5SC022842	SCBBR6ZGXSC022819
SCBCF13S0SC022857	SCBDR4ZG2SC022567	SCBBF53S7SC022860
SCBCF13S4SC022666	SCBDR4ZG9SC022579	SCBBL53S7SC022821
SCBCF13S4SC022828	SCBCF13S0SC022843	SCBBL53SXSC022750
SCBCF13S6SC022796	SCBCF13S2SC022889	SCBCF13S1SC022897
SCBCF1ZG1SC022871	SCBCF13S8SC022881	SCBCF13S2SC022892
SCBCF1ZG6SC022770	SCBCL13S0SC022883	SCBCF13S3SC022903
SCBCG13SXSC022832	SCBCL13S1SC022861	SCBCL13S2SC022884
SCBCJ13S1SC022672	SCBCL13S6SC022838	SCBCL13S4SC022921
SCBCL13S0SC022818	SCBCP2ZG5SC022830	SCBCL13S7SC022900
SCBCL13S3SC022859	SCBCR2ZG5SC022854	SCBCL13S7SC022931
SCBCL13S7SC022850	SCBCR2ZG6SC022877	SCBCL13S8SC022890
SCBCL13S8SC022713	SCBCR2ZGXSC022879	SCBCL13SXSC022924
SCBCR2ZG6SC022538	SCBDF33S5SC022773	SCBCP2ZG3SC022888
SCBDF33S5SC022630	SCBDF33S7SC022841	SCBCP2ZG5SC022908
SCBDG33S3SC022543	SCBDL33S4SC022868	SCBCR13S4SC022917
SCBDP4ZG4SC022866	SCBDL33S6SC022810	SCBDL33S6SC022872
SCBDP4ZG9SC022846	SCBDL33S9SC022820	SCBDP4ZG6SC022836
SCBDR4ZG2SC022598	SCBDP4ZG8SC022899	SCBDR4ZGXSC022929
SCBDR4ZG3SC022724	SCBDP4ZG9SC022894	SCBCF13S6SC022913
SCBCF13S5SC022823	SCBDR4ZG4SC022893	SCBDF33S8SC022864
SCBBR6ZGXSC022450	SCBBF53S5SC022825	SCBBF53S0SC022909
SCBBF53S3SC022757	SCBBF5ZG2SC022607	SCBBF53S2SC022815
SCBBF53S7SC022664	SCBBG53S4SC022876	SCBBF53S6SC022901
SCBBF5ZG7SC022862	SCBBL53S8SC022858	SCBBG53S5SC022837
SCBBG53S2SC022522	SCBBP6ZG2SC022898	SCBBL53S1SC022927
SCBBL53S4SC022744	SCBBP6ZG6SC022726	SCBBP6ZG1SC022911
SCBBL53S4SC022808	SCBBP6ZG8SC022873	SCBBP6ZG8SC022775
SCBBP6ZG6SC022855	SCBBR6ZG1SC022806	SCBBP6ZGXSC022907

SCBBR53S7SC022834	SCBCL13SXSC023006	SCBCL13SXSC022938
SCBBR6ZG1SC022885	SCBCR2ZG1SC022995	SCBCP2ZG0SC022993
SCBBR6ZG2SC022829	SCBDF33S2SC022696	SCBCP2ZG6SC023002
SCBBR6ZG6SC022817	SCBDF33S3SC022948	SCBCR2ZG9SC023022
SCBBR6ZG8SC022849	SCBDF33S7SC022905	SCBDF33S1SC023015
SCBBL53S5SC022882	SCBDL33S0SC022916	SCBDL33S2SC022951
SCBBL53S8SC022844	SCBDL33S2SC022934	SCBDP4ZG0SC022802
SCBCF13S7SC022869	SCBDL33SXSC022910	SCBDR4ZG0SC022941
SCBCJ13S0SC022923	SCBDP4ZG0SC022945	SCBDR4ZG4SC022926
SCBCL13S0SC022950	SCBDR4ZG5SC022126	SCBDR4ZG9SC022999
SCBCL13S6SC022886	SCBCF13S5SC023003	SCBCL13S0SC023032
SCBCL13S6SC022919	SCBBF53S1SC022918	SCBCF13SXSC023000
SCBCL13S8SC022906	SCBBF5ZGXSC022936	SCBDF33S3SC022870
SCBCP2ZG8SC022949	SCBBG53S5SC022711	SCBBG53S1SC022382
SCBCR2ZG1SC022947	SCBBG53SXSC022851	SCBBF53S9SC023041
SCBCR2ZG7SC022533	SCBBJ53S0SC022732	SCBBG53S6SC022636
SCBCR2ZG7SC022953	SCBBL53S7SC022933	SCBBR6ZG1SC023017
SCBCR2ZGXSC022932	SCBBR53S0SC022920	SCBBR6ZG2SC022880
SCBDF33S1SC022902	SCBBR53S2SC022952	SCBBR6ZG2SC022930
SCBCF13S9SC022937	SCBBR6ZG0SC023008	SCBBR6ZG2SC023012
SCBBG53S2SC022942	SCBBR6ZG9SC022925	SCBBR6ZG5SC022792
SCBBG53S8SC022895	SCBBR6ZGXSC022867	SCBBR53S1SC023039
SCBBP6ZG9SC022994	SCBCF13S6SC022510	SCBCL13S0SC022446
SCBBP6ZGXSC022891	SCBCF13S9SC023019	SCBCF13S9SC022954
SCBBR6ZG4SC022914	SCBCF13S9SC023036	SCBCJ13S6SC023025
SCBBR6ZG5SC022887	SCBCF13SXSC022865	SCBCL13S0SC023046
SCBCF13S6SC022670	SCBCF13SXSC023028	SCBCL13S1SC023038
SCBCF13S2SC022939	SCBCL13S2SC022996	SCBCL13S2SC023081
SCBCF13S6SC022944	SCBCL13S6SC022998	SCBCL13S3SC022845
SCBCF13S6SC023009	SCBCL13S7SC023013	SCBCL13S3SC023056
SCBCG13S9SC022935	SCBCL13SXSC022874	SCBCL13S4SC023065

SCBCL13S6SC023018	SCBBR6ZG4SC023058	SCBDL33S5SC023110
SCBCL13SXSC023037	SCBBR6ZG5SC022839	SCBDR4ZG1SC023063
SCBCL13SXSC023054	SCBCJ13SXSC022413	SCBDR4ZG8SC023108
SCBCR13S7SC023043	SCBDJ33S8SC022491	SCBBF5ZG2SC023093
SCBCR2ZG8SC022928	SCBCF13S5SC023096	SCBBF5ZG5SC022407
SCBDF33S5SC023034	SCBCF13S8SC022718	SCBBP6ZG1SC023055
SCBDF33SXSC023031	SCBCF1ZG3SC023083	SCBBP6ZGXSC023023
SCBCF13S8SC023061	SCBCG13S2SC023120	SCBBR53S4SC023097
SCBDF33S0SC023040	SCBCL13S3SC023090	SCBBR6ZG5SC023067
SCBBF53SXSC023047	SCBCL13S4SC023101	SCBBF53S4SC023111
SCBBG53S7SC023004	SCBCL13S6SC023049	SCBBR53S9SC023144
SCBBG53S7SC023035	SCBCL13S7SC023044	SCBCG13S1SC022573
SCBBP6ZG4SC023020	SCBCL13S7SC023092	SCBCR2ZG1SC022852
SCBBP6ZG9SC023014	SCBCL13S9SC023059	SCBCF13S1SC023158
SCBBR53S0SC023033	SCBCP2ZG0SC023075	SCBCF13S2SC023086
SCBBL53S5SC022431	SCBCP2ZG9SC023107	SCBCF13S6SC022863
SCBCF13S3SC023050	SCBCR2ZGXSC023109	SCBCF13S9SC023117
SCBCF1ZG2SC023088	SCBDF33S6SC023060	SCBCJ13S0SC023134
SCBCG13S6SC023024	SCBDL33S2SC023095	SCBCL13S1SC023069
SCBCG13S9SC023115	SCBDL33S4SC023051	SCBCL13S1SC023119
SCBCL13S0SC023077	SCBDP4ZG3SC023071	SCBCL13S2SC023131
SCBCP2ZG3SC023068	SCBDR33S0SC023076	SCBCL13S2SC023145
SCBCP2ZG6SC022822	SCBCF13S0SC023099	SCBCL13S4SC023163
SCBCR2ZG9SC023084	SCBCF13S3SC023064	SCBCL13S8SC023103
SCBDP4ZG4SC023029	SCBCF13S5SC023132	SCBCL13S9SC023112
SCBDR4ZG2SC023072	SCBCG13S7SC023128	SCBCL13S9SC023157
SCBCF13S6SC023057	SCBCL13S1SC023136	SCBCL13SXSC023152
SCBBG53S5SC022708	SCBCR2ZG6SC023141	SCBCL13SXSC023166
SCBBG53SXSC023062	SCBDF33S4SC023087	SCBCP2ZG2SC023126
SCBBL53S8SC022875	SCBDF3ZG8SC022415	SCBDF33S2SC023105
SCBBR6ZG2SC022717	SCBDL33S0SC023113	SCBDF33S4SC023137

SCBDF33S5SC023048	SCBCL13S9SC023188	SCBCG13S0SC023021
SCBDL33S5SC023074	SCBCL13S9SC023207	SCBCG13S6SC023234
SCBDL33S5SC023124	SCBDF33S6SC023155	SCBCL13S0SC023189
SCBDP4ZGXSC023133	SCBDF33S7SC023181	SCBCL13S1SC023251
SCBBL53S7SC023001	SCBDF33S8SC023089	SCBCL13S3SC023154
SCBBP6ZG0SC022799	SCBDF33S8SC023139	SCBCL13S4SC023213
SCBBJ53S6SC023027	SCBDF33S9SC023005	SCBCL13S5SC023236
SCBBL53SXSC022781	SCBDF33S9SC023098	SCBCL13S7SC023240
SCBBP6ZG1SC023122	SCBDL33S1SC023167	SCBCL13S7SC023254
SCBBP6ZG2SC023114	SCBDL33S6SC023116	SCBCL13S8SC023201
SCBBR53S3SC023091	SCBDL33S6SC023200	SCBCP2ZG3SC022745
SCBCF13S1SC023127	SCBDL33S9SC022896	SCBCR2ZG9SC023229
SCBCF13S7SC023195	SCBDL33SXSC023183	SCBDF33S5SC023230
SCBCF1ZG0SC023168	SCBDR33S6SC023129	SCBDL33S0SC023242
SCBCF1ZG1SC023146	SCBDR4ZG3SC023100	SCBDL33S4SC023227
SCBCP2ZG9SC023138	SCBBP6ZG8SC022680	SCBDL33S6SC023150
SCBCP2ZGXSC023178	SCBBF53S0SC023171	SCBDP4ZG1SC023215
SCBCR2ZG7SC023147	SCBBF53S5SC022615	SCBDP4ZG6SC022738
SCBDP4ZG4SC023175	SCBBG53S0SC023118	SCBDR4ZG4SC023185
SCBBG53S7SC023164	SCBBR53S6SC022940	SCBDR4ZG8SC023187
SCBBL53S9SC023162	SCBBR6ZG6SC023191	SCBDR4ZGXSC023143
SCBCF13S0SC023202	SCBDP4ZGXSC022449	SCBBL53S6SC022955
SCBCF13S5SC023194	SCBCF13S2SC023184	SCBBF53S3SC023231
SCBCF13S8SC023206	SCBCF13S4SC023249	SCBBG53S0SC023233
SCBCL13S0SC023192	SCBCF13S6SC022992	SCBBG53S8SC023237
SCBCL13S1SC023170	SCBCF13S6SC023172	SCBBL53S9SC023193
SCBCL13S1SC023198	SCBCF13S8SC023223	SCBBP6ZG8SC023179
SCBCL13S1SC023203	SCBCF13S9SC023151	SCBBR53S2SC023082
SCBCL13S3SC022912	SCBCF13SXSC023174	SCBBR6ZG3SC023228
SCBCL13S4SC023177	SCBCF13SXSC023241	SCBBR6ZG4SC023030
SCBCL13S6SC023066	SCBCF1ZG4SC023190	SCBCR2ZGXSC022753

SCBCF13S1SC023211	SCBDF33S6SC023284	SCBCL13S4SC023342
SCBCF13S7SC023245	SCBDF33S8SC023173	SCBCL13S7SC023304
SCBCF13S7SC023259	SCBDF33S9SC023313	SCBCR2ZG2SC023296
SCBCG13S6SC023007	SCBDL33S0SC023287	SCBDF33S4SC023297
SCBCL13S5SC023219	SCBDL33S4SC023258	SCBBF53S5SC023280
SCBCP2ZG6SC023260	SCBDR4ZG0SC023250	SCBBP6ZG6SC023312
SCBCP2ZG7SC023221	SCBDR4ZG6SC023267	SCBBR6ZG1SC023261
SCBCR2ZG4SC023123	SCBBP6ZG5SC022734	SCBBR6ZG9SC023301
SCBCR2ZG8SC023268	SCBBP6ZG7SC022699	SCBCF1ZG4SC022430
SCBDG33SXSC023222	SCBBR6ZG1SC022997	SCBCG13S8SC023073
SCBDP4ZG6SC023212	SCBBF53S6SC023160	SCBDF33S2SC023010
SCBBF53SXSC022853	SCBBF53S6SC023286	SCBCF13S0SC023278
SCBBF53SXSC023226	SCBBF5ZG5SC023248	SCBCF13S1SC023080
SCBBG53S8SC023125	SCBBG53S0SC023149	SCBCF13S3SC023291
SCBBL53S7SC023239	SCBBG53S1SC023306	SCBCF13S4SC023302
SCBBP6ZG2SC023243	SCBBG53S3SC023257	SCBCF13S4SC023316
SCBBR53S0SC023274	SCBBG53S7SC023276	SCBCF13S4SC023350
SCBBR6ZG6SC023224	SCBBG53S9SC023053	SCBCF13SXSC023353
SCBCF13S1SC023273	SCBBL53S2SC023293	SCBCG13S6SC023282
SCBCF13S8SC022878	SCBBL53S3SC023142	SCBCL13S7SC023299
SCBCG13S5SC023225	SCBBL53S5SC023255	SCBCL13S8SC023344
SCBCG13S6SC023217	SCBBL53S6SC023135	SCBCL13S8SC023358
SCBCG13S9SC023244	SCBBL53S6SC023216	SCBCP2ZG8SC023311
SCBCL13S8SC023196	SCBBP6ZGXSC023264	SCBDF33S3SC023307
SCBCL13S9SC023269	SCBBR6ZG0SC023106	SCBDF33S5SC023292
SCBCP2ZG1SC023263	SCBBR6ZG0SC023283	SCBDL33S6SC023262
SCBCP2ZG3SC023247	SCBBR6ZG7SC023281	SCBDL33S6SC023357
SCBCR13S4SC023016	SCBBR6ZG7SC023295	SCBDL33S8SC023277
SCBDF33S1SC022589	SCBCF13S2SC023279	SCBDP4ZG5SC023315
SCBDF33S1SC023256	SCBCF13S6SC023026	SCBBF53S6SC022946
SCBDF33S6SC023253	SCBCG13S1SC023318	SCBBF53S0SC023199

SCBBF53S5SC022856	SCBDL33SXSC023300	SCBDL33S6SC023407
SCBBF53S7SC023359	SCBBF53SXSC023341	SCBDL33S7SC023433
SCBBF5ZG7SC023218	SCBBG53S4SC023266	SCBDL33S8SC023246
SCBBG53S8SC023156	SCBBG53S5SC023390	SCBDP4ZG0SC023271
SCBBG53S8SC023335	SCBBG53S8SC023366	SCBDP4ZG2SC023384
SCBBL53SXSC023333	SCBBL53S1SC023169	SCBDP4ZG4SC023404
SCBBP6ZG5SC023317	SCBBL53S3SC023383	SCBDR4ZG1SC023421
SCBBR6ZG4SC023352	SCBBP6ZG0SC023337	SCBBF53S5SC023070
SCBBR6ZG6SC023210	SCBBP6ZG5SC023270	SCBBF53S9SC023413
SCBBR6ZG7SC023197	SCBBP6ZG6SC023410	SCBBG53SXSC023417
SCBBR6ZG9SC023363	SCBBR6ZG0SC023042	SCBBL53S4SC023392
SCBCF13S0SC023362	SCBBR6ZG0SC023381	SCBCF13S5SC023373
SCBCF13S3SC023338	SCBBR6ZG3SC023214	SCBCF13S7SC023455
SCBCF13S3SC023386	SCBBR6ZGXSC023372	SCBCF13S9SC023473
SCBCF13S9SC023294	SCBCF13S0SC023393	SCBCG13S0SC023441
SCBCG13S2SC023408	SCBCF13S0SC023412	SCBCL13S1SC023461
SCBCJ13S6SC023395	SCBCF13S1SC023399	SCBCR2ZG1SC023368
SCBCL13S7SC023397	SCBCF13S1SC023435	SCBDF33S7SC023391
SCBCL13S8SC023361	SCBCF13S3SC023159	SCBDF33S9SC023439
SCBCL13S8SC023375	SCBCF13S6SC023382	SCBDL33S5SC023396
SCBCL13S9SC023367	SCBCF13S7SC023052	SCBDL33SXSC023443
SCBCP2ZG8SC023356	SCBCF13S7SC023388	SCBDR4ZG0SC023085
SCBCR13S5SC023364	SCBCF13S8SC023416	SCBBG53S0SC023426
SCBCR2ZG0SC023314	SCBCG13S3SC023305	SCBBG53S6SC023401
SCBCR2ZG4SC023235	SCBCL13S0SC023161	SCBBG53S9SC023165
SCBDF33S1SC023371	SCBCL13S5SC023379	SCBDP4ZG5SC023380
SCBDJ3ZG0SC023265	SCBCL13S5SC023432	SCBCL13S9SC022915
SCBDL33S2SC023310	SCBCP2ZG7SC023428	SCBCF13S1SC023452
SCBDL33S4SC023289	SCBDF33S3SC023209	SCBCF13S2SC023430
SCBDL33S5SC023351	SCBDL33S3SC023400	SCBCF13S5SC023437
SCBDL33S6SC023343	SCBDL33S6SC023374	SCBCF13S8SC023447

SCBCG13S3SC022848	SCBCP2ZG3SC023488	SCBCR2ZG7SC023486
SCBCL13S2SC023467	SCBCP2ZGXSC023519	SCBDF33S4SC023414
SCBCL13S9SC023370	SCBCR13S4SC023419	SCBDL33S9SC023451
SCBCP2ZG0SC023402	SCBCR13S8SC023424	SCBDP4ZG2SC023482
SCBCP2ZG0SC023450	SCBDF33S3SC023369	SCBDP4ZG5SC023444
SCBCP2ZG7SC023445	SCBDF33S6SC023334	SCBDP4ZG6SC023503
SCBCR13S6SC023308	SCBDF33S9SC023487	SCBDP4ZG7SC023509
SCBCR23S4SC023376	SCBDL33S4SC022692	SCBCG13SXSC023544
SCBDF33S1SC023340	SCBDL33SXSC023409	SCBDL33S7SC023528
SCBDF33S6SC023303	SCBDP4ZG1SC023506	SCBBF53S1SC023521
SCBDF33SXSC023465	SCBDR4ZG2SC023475	SCBBF53SXSC023534
SCBDL33S3SC023431	SCBBF5ZG5SC023458	SCBBF5ZG8SC023079
SCBDL33S4SC023387	SCBBG53S0SC023491	SCBBG53S6SC023186
SCBDL33S4SC023423	SCBBG53S5SC023504	SCBBG53SXSC023398
SCBDL33S8SC023425	SCBBG53S6SC023480	SCBBL53S4SC023456
SCBDL33SXSC023457	SCBBG53S8SC023500	SCBBL53S7SC023290
SCBDP4ZGXSC023360	SCBBL53S6SC023460	SCBBR53S6SC023523
SCBBF53SXSC023405	SCBBP6ZG2SC023436	SCBBR53S7SC023045
SCBBG53S4SC023462	SCBBP6ZG5SC023446	SCBBR6ZG0SC023347
SCBBL53S6SC023474	SCBBP6ZG7SC023478	SCBBR6ZG1SC023518
SCBBP6ZG5SC023429	SCBBR53S0SC023453	SCBBR6ZG6SC023496
SCBBR53S2SC023440	SCBBR53SXSC023489	SCBBR6ZG6SC023532
SCBBR6ZG3SC023309	SCBBR6ZG9SC023377	SCBBL53S7SC023502
SCBBR53S4SC023469	SCBDL33S2SC023484	SCBDL33S0SC023418
SCBBR6ZGXSC023422	SCBCF13S0SC023510	SCBBG53S8SC023349
SCBCF13S1SC023483	SCBCF13S5SC023180	SCBBF53S1SC023471
SCBCF13S2SC023511	SCBCF13S8SC023481	SCBBF53S7SC023345
SCBCF13S4SC023512	SCBCL13S3SC023011	SCBBG53S1SC023550
SCBCG13S2SC023148	SCBCL13S4SC023406	SCBBG53S5SC023485
SCBCL13S9SC023479	SCBCL13S6SC023505	SCBBJ53S7SC023182
SCBCL13S9SC023515	SCBCL13S9SC023529	SCBBL53S1SC023527

SCBBR6ZG0SC023204	SCBBG53SXSC023563	SCBBP6ZG1SC023640
SCBBR6ZG0SC023543	SCBBL53S9SC023565	SCBBP6ZG4SC023602
SCBBR6ZG5SC023540	SCBBP6ZG5SC023298	SCBBP6ZG6SC023102
SCBBR6ZG9SC023508	SCBCF13S1SC023533	SCBBP6ZG7SC023559
SCBCF13S1SC023564	SCBCL13SXSC023121	SCBBP6ZG8SC023568
SCBCF13S2SC023556	SCBDF33S4SC022621	SCBBP6ZG8SC023618
SCBCF13S3SC023579	SCBDF33S9SC023554	SCBBP6ZG9SC023613
SCBCF13S4SC022943	SCBDP4ZG0SC023562	SCBBR53S3SC023608
SCBCF13SXSC023501	SCBBF53S0SC023574	SCBBR53S4SC023553
SCBCF13SXSC023546	SCBBF53S0SC023672	SCBBR53S5SC023514
SCBCF13SXSC023580	SCBBF53S6SC023403	SCBBR63S9SC023599
SCBCG13SXSC023558	SCBBF53S7SC023586	SCBBR6ZG1SC022904
SCBCL13S0SC023094	SCBBF53S7SC023653	SCBBR6ZG3SC022922
SCBCL13S1SC023492	SCBBF53S8SC023516	SCBBR6ZG4SC023643
SCBCL13SXSC023507	SCBBG53S0SC023605	SCBBR6ZG6SC023434
SCBCL13SXSC023572	SCBBG53S2SC023623	SCBBR6ZG7SC023555
SCBCP2ZG1SC023389	SCBBG53S3SC023629	SCBBR6ZG8SC023645
SCBCR23S9SC023552	SCBBG53S4SC023476	SCBBR6ZGXSC023632
SCBDF33S2SC023542	SCBBG53S5SC023454	SCBCF13S0SC023619
SCBDG33S1SC022444	SCBBG53S6SC023611	SCBCF13S0SC023636
SCBDJ33S4SC023539	SCBBG53S7SC023438	SCBCF13S0SC023684
SCBDL33S4SC023566	SCBBG53S7SC023570	SCBCF13S3SC023498
SCBDL33S5SC023365	SCBBG53S7SC023634	SCBCF13S3SC023680
SCBDL33S5SC023463	SCBBG53S8SC023660	SCBCF13S4SC023459
SCBDL33SXSC023524	SCBBG53S9SC023537	SCBCF13S5SC023549
SCBDP4ZG0SC023531	SCBBG53S9SC023666	SCBCF13S5SC023664
SCBDP4ZG8SC023275	SCBBG53SXSC023594	SCBCF13S7SC023584
SCBBF5ZG7SC023557	SCBBL53S0SC023597	SCBCF13S7SC023603
SCBBG53S1SC023581	SCBBL53S1SC023592	SCBCF13S7SC023648
SCBBG53S6SC023589	SCBBL53S3SC023626	SCBCF13S8SC023593
SCBBG53S8SC023576	SCBBP6ZG1SC023637	SCBCF13S8SC023609

SCBCF13S9SC023652	SCBDJ33S8SC023687
SCBCF1ZG6SC023630	SCBDL33S0SC023631
SCBCG13S3SC023577	SCBDL33S0SC023659
SCBCG13S7SC023176	SCBDL33S1SC023573
SCBCJ13SXSC023657	SCBDL33S1SC023654
SCBCL13S3SC022800	SCBDL33S1SC023668
SCBCL13S3SC023638	SCBDL33S2SC023551
SCBCL13S4SC023681	SCBDL33S3SC023591
SCBCL13S5SC023575	SCBDL33S3SC023607
SCBCL13S8SC023571	SCBDL33S4SC023499
SCBCL13S8SC023585	SCBDL33S4SC023650
SCBCL13S8SC023621	SCBDL33S5SC023642
SCBCL13S9SC023661	SCBDL33S7SC023545
SCBCP2ZG3SC023538	SCBDP4ZG2SC023238
SCBCP2ZG4SC023600	SCBDP4ZG4SC023614
SCBCP2ZG8SC023678	SCBDP4ZG5SC023220
SCBCP2ZG9SC023656	SCBDP4ZG8SC023468
SCBCP2ZG9SC023673	SCBDP4ZG9SC023477
SCBCP2ZGXSC023651	SCBDP4ZG9SC023625
SCBCR13S5SC023526	SCBDP4ZGXSC023598
SCBCR23S1SC023612	SCBDR43S8SC023378
SCBCR23S3SC023658	SCBDR4ZG3SC023517
SCBCR23S9SC023339	SCBDR4ZG6SC023205
SCBCR2ZG1SC023354	SCBDR4ZG6SC023348
SCBCR2ZG7SC023522	SCBDR4ZG6SC023513
SCBDF33S1SC023578	
SCBDF33S1SC023595	
SCBDF33S1SC023662	
SCBDF33S3SC023520	
SCBDF33S5SC023535	
SCBDF33S5SC023583	