

Vehicle-specific service

Topic	01 PSS Engine control unit drive system faults P060C00, and U041600
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2072710/6
Level	EH
Status	Released for publishing
Release date	Jun 12, 2025

Vehicle data

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
8W*	2023	A		DMSA	*	*
8W*	2022	A		DMSA	*	*
F5*	2023	A		DMSA	*	*
F5*	2022	A		DMSA	*	*
F5*	2025	A		DMSA	*	*
F5*	2024	A		DMSA	*	*
8W*	2025	A		DMSA	*	*
8W*	2024	A		DMSA	*	*
FY*	2025	A		DMSA	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
WA1	*	FY	*	S	*	000001	999999		
WAU	*	F5	*	R	*	000001	999999		
WA1	*	F4	*	P	*	000001	999999		
WAU	*	F4	*	N	*	000001	999999		
WAU	*	F5	*	N	*	000001	999999		
WA1	*	F4	*	R	*	000001	999999		
WAU	*	F4	*	R	*	000001	999999		
WAU	*	F5	*	P	*	000001	999999		
WAU	*	F4	*	P	*	000001	999999		
WA1	*	F4	*	N	*	000001	999999		

Control units

Diagnostic address	Software part number	Software version	Hardware part number	Hardware version
0001 - Engine electronics	*80A*.907.115.C*	0001	*06N*.907.309.A*	H80
0001 - Engine electronics	*80A*.907.115.B*	0001	*06N*.907.309.A*	H80
0001 - Engine electronics	*80A*.907.115.B*	0003	*06N*.907.309.A*	H80
0001 - Engine electronics	*80A*.907.115.C*	0002	*06N*.907.309.A*	H80
0001 - Engine electronics	*8W0*.907.115.AM	*	*	*
0001 - Engine electronics	*80A*.907.115.B*	0002	*06N*.907.309.A*	H80

Documents

Document name
master.xml

Condition

REVISION HISTORY		
Revision	Date	Purpose
6	-	Revised <i>Service</i> (updated expected release date)
5	04/03/2025	Revised header (updated models)
4	12/19/2024	Revised header (added MY)
		Revised <i>Condition</i> (updated customer statement)
		Revised <i>Service</i> (updated expected release date)

This bulletin applies to MY22-25 A4, A5, Q5 vehicles only.

Customer states:

- The EPC Lamp lights up.
- “Drive system: fault” appears in the instrument cluster.

Workshop findings:

The following DTC are stored in the Engine Control Unit -J623- (address word 0001):

- **P060C00** – “Internal Control Module Main Processor with Symptom Code DFCC 44160”.
- **U041600** – “Invalid Data Received From Vehicle Dynamics Control Module with Symptom Code DFCC 34193”.

Technical Background

Software issues within the Engine Control Unit.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

1. If the customer’s vehicle condition matches the condition listed in the *Technical Background* of this PSS TSB, explain to the customer that there may be multiple lights on dash but will not affect the performance of the vehicle. Explain to the customer that a solution is expected Q3 of 2025 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer’s concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

For MY2022-2024 Q5 40, please refer to TSB 2076356: *01 Engine control unit drive system faults P060C00 and U041600*.



NOTICE

In many cases, the complaint is fixed after an ignition cycle.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2072710**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©**2025 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.