



SSM 54054 2025 Transit - Gasoline/Flex Fuel Engine - Illuminated Powertrain Malfunction (Wrench) Indicator With DTCs P0773 And/Or P097E Stored In The PCM

Some 2025 Transit vehicles with gasoline or flex fuel engines may exhibit an illuminated powertrain malfunction (wrench) indicator with diagnostic trouble codes (DTCs) P0773 and/or P097E stored in the powertrain control module (PCM). These vehicles may also exhibit various other powertrain related DTCs setting in the PCM. This may be due to pushed out pins and/or poor terminal crimping at connector C1280. Refer to Wiring Diagram Cell 30-5 for location information.