

9100325

10/02/2025

MY 24 GG 25 DT 19-23, 19-20 KL 18-24,
18-20 JL 24 MP 22-23 BV 22-23 WL 17-24,
21-24 GA 21-24 J6 23-25 WS 19-23, 19-20
K8 18-24 GU 24 GV

GPOP - Issue Review System

Part Number: 05281586A\$, 68337662A\$, 68360098A\$, 68565193A\$

Part Description: VALVE, Purge Control

Issue Description: Before replacing any parts please refer to SOL S2518000008 if it applies to the vehicle you are working on based on a VIN search in Service Library. Before replacing this part due to Engine Light On with P1CEA (Boost Side EVAP Purge System Performance), check for:
1) Improperly connected or kinked/pinched Purge Hoses at the Ejector Tees on the Air Box or Duct. 2) Improperly connected or kinked/pinched Purge Hose at the Purge Solenoid or OBD Valve. 3) Improperly connected or kinked/pinched Purge Hose at the Intake. 4) Check for the correct Purge Hoses installation.