



STAR ONLINE PUBLICATION



Case Number: S2308000035 REV. C

Release Date: October 2025

Symptom/Vehicle Issue: U1202-00 Lost Communication with Electric Vehicle Control Module Set Erroneously in The Radio (ETM)

Technician Observation: No owner complaint, DTC present when scanning.

Discussion: When scanning the vehicle for Diagnostic Trouble Codes (DTCs) you may find an Active U1202-00 Lost Communication with Electric Vehicle Control Module setting as stored in the Radio (ETM).

The 2.0L GME engine equipped in the Dodge Hornet may inadvertently set a U1202-02 when it does not have the electrified powertrain components. Stored codes can be cleared if there are no owner complaints associated with this DTC.

For vehicles that have an owner complaint and this DTC, follow the normal Service Library diagnostics for this DTC and verify the ETM, BCM, IPC and PCM have no associated updates available for this issue.

Do Not Replace Any Components For This DTC

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found