



Service Bulletin

Bulletin No.: PIP6077B

Date: October, 2025

PRELIMINARY INFORMATION

Subject: 8T45 VT40 P07E5 / P073E No Drive and / or No Reverse

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2025		All	All	All	All
GMC	Terrain	2025		All	All	All	All

Involved Region or Country	U.S. Only
Condition	Some Chevrolet and GMC vehicles equipped with the 8T45 MGH or VT40 MRQ automatic transmission may experience: No drive and or no reverse and a SES light on with code/s P07E5 and or P073E after an Over The Air update.
Cause	Engineering is investigating the concern.

Correction

If the vehicle has a customer concern of no drive and/or no reverse with a SES light on and DTC(s) P07E5 and/or P073E set current/history, then perform the following:

Clear DTCs using GDS2, disconnect the MDI2 from the vehicle, allow the vehicle to power down for 10 minutes and then retest the vehicle to see if the concern returns.

If the concern is resolved after the above procedure, then no additional diagnostics is necessary, and no hardware replacements are necessary. Vehicle can be released to customer.

If the concern does return, then follow normal SI diagnostics.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8481178*	Clear DTCs and power cycle following OTA	.3 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version	3
Modified	07/30/2025 Created 08/25/2025 Update to the correction 10/30/2025 Update the correction and added labor op.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.