

## **GPOP - Issue Review System**

**Part Number:** 68457701a\$

**Part Description:** SENSOR, Ambient Temperature

---

**Issue Description:** The ambient temperature sensor mounted on the mirror may read higher than expected, sensor must NOT be removed before reviewing the following cases. There are two cases:

1) DTC codes are present, proceed according to the following TSBs:

1.1) 18-031-25 (25 MY DT with DTC:  
P0071-00 & P0073-00) 1.2) 18-032-25 (25 MY DT with DTC:  
P0071-00 & P0073-00 for vehicles built on or after July 01, 2024 and before July 29, 2025)

1.3) 08-357-25 (26 MY DT with DTC:  
P0071-00 & P0073-00) 2) No DTC codes are present, but temperature shown in the cluster/radio is higher than expected, proceed according to SOL S2508000078. To allow the sensor to update properly, drive the vehicle at highway speeds (above 20 MPH) for several miles (15 minutes). This ensures sufficient airflow and temperature sampling for accurate readings. If the temperature still does not update, proceed with standard diagnostic procedures.