

On-car analysis list from November 12th, 2025
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Cross Sport	24-26	All	All	Oil Leak	Oil leak from Cylinder Head Cover (Untouched vehicles) (MY24 after engine serial DRK 154894)
	Atlas, Cross Sport	25-26	All	All	MIL on P0456/P0442/P04F0 Purge Valve Stuck Open	Customer states MIL-on, P0456, P0442, or P04F0 stored in ECM memory (Untouched Vehicles)
	Taos	25-26	1.5 DYBA	All	MIL on P2080 Exhaust Gas Temperature Sensor Fault	Customer states MIL-on, fault P2080 present (Untouched Vehicles)
	Jetta	25	1.5 DNKA	All	DTC P0461 Stored In ECM	Customer states MIL-on (Untouched Vehicles)
Electric	Atlas, Cross Sport	25	All	All	DTC Active U108E00 Stored In AW19/DA0019 Control Unit In Steering Wheel No Communication	Customer states various error messages on the cluster (Untouched vehicles)
Body	Atlas, Atlas Cross Sport, Jetta, Taos	25-26	All	All	A/C Inop, Leaking from Condenser at the Drier Cap	Customer states A/C Inop, no cooling (Untouched vehicles)
	Tiguan	24	All	All	Striker Plate	Customer states wind noise and or water ingress (Untouched vehicles)
Chassis	Atlas, Cross Sport	24-26	All	All	Front Brake Noise	Customer states front brake noise/premature uneven pad wear (Untouched vehicles)
	Golf R, GTI	24-25	All	All	Front Strut Noise	Customer states there is a noise coming from the front strut areae (Untouched vehicles)
	Atlas, Cross Sport	24-26	All	All	Front Outer CV Boot Leaking	Customer states there is a leak from the front of the vehicle (Untouched vehicles)
	Tiguan	22-24	All	All	Brake Caliper Noise	Customer states there is a noise from the front of the vehicle (Untouched vehicles)