

Field campaign

Topic	Baseline Software Update from BiL 5.2.1 to BiL 5.3.1 v2 (NAR Only) (SC25/07)
Market area	United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2077308/8
Campaign number	ED37
Note	
Type	
US code	

Vehicle data

25MY Continental GT & GTC

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
Z23*	2025	E		*	*	*
Z24*	2025	E		*	*	*

Documents

Document name
master.xml
ed37svmcode.pdf
ed37vinlist.pdf

ED37

Transaction No.: 2077308/8

Baseline Software Update from BiL 5.2.1 to BiL 5.3.1 v2 (NAR Only) (SC25/07)

Release date: Nov 24, 2025

Notes

▼ **Repair instructions**

Technical background

Software updates must be applied to update the vehicles Baseline Level.

The software update corrects the following Diagnostic trouble codes:

- P060100: High Voltage Battery (Address 008C) Internal Control Module Memory Checksum Error
- P057F00: Battery "A" State of Charge Performance, B11B300 Igniter for high voltage battery interrupt
- P0A0B00: High Voltage System Interlock Circuit Performance (HVIL).



CAUTION

If the ED35 Campaign is showing as outstanding in ElsaPro, the ED35 campaign **MUST** be completed first.

Remedy

The instructions within the 'Work' section **must** be conducted to completion.

Customer notification

Please ensure all applicable instructions are conducted at the nearest opportunity.

Warranty

SVM Update Time

Claim type: 790 or 710

Service number: ED37

Damage code: 0066

Criteria: 01

Labour Operation Code: 01 51 00 00

Time: As per ODIS log (Must not exceed 200TU)

Additional Time Allowance

A 100TU allowance may be claimed only if a SVM update fails to complete successfully. This is intended to cover additional diagnostic or recovery work directly resulting from the failed update. It must not be used for unrelated delays or issues.

ODIS logs must be attached to a DISS ticket for evidence of failure. Claims without valid documentation will be rejected. Warranty Adjudicators will review associated ODIS logs and DISS queries to determine actual software update time.

Parts

Not Applicable

Parts supply

Not Applicable

Parts despatch control

Not Applicable

Repair instructions



Technical background

Software updates must be applied to update the vehicles Baseline Level.

The software update corrects the following Diagnostic trouble codes:

- P060100: High Voltage Battery (Address 008C) Internal Control Module Memory Checksum Error
- P057F00: Battery "A" State of Charge Performance, B11B300 Igniter for high voltage battery interrupt
- P0A0B00: High Voltage System Interlock Circuit Performance (HVIL).

CAUTION

If the ED35 Campaign is showing as outstanding in ElsaPro, the ED35 campaign **MUST** be completed first.

Check

Check if the vehicle is already listed as repaired in "Repair history" (in ElsaPro).

Please also refer to the "Identification" section and check if a paint identification mark is evident in the vehicle.

If the vehicle is not shown in ElsaPro as repaired, and the identification mark is not present, please conduct the instructions within the 'Work' section to completion

Parts

Not Applicable

Work





CAUTION

The Bentley ODIS-S Brand Version MUST be at least 2.35.1 (or higher)



CAUTION

Before conducting the onward instructions, the operative **MUST** recheck the communication method in ODIS and ensure that DoIP is selected before proceeding. Within ODIS-S, perform the following:

- On the right hand side, select the “Admin” tile (Within ‘Operating modes’)
- Select “GFF sequence” (Within ‘General information’ section)
- Under the “Selection of Communication path” drop-down menu, select “Only permit DoIP communication”.



CAUTION

DO NOT, UNDER ANY CIRCUMSTANCES, ATTEMPT TO CONDUCT THE SOFTWARE UPDATE VIA THE CAN NETWORK. ONLY DoIP SHOULD BE USED WHEN PERFORMING THE SVM UPDATE.



CAUTION

You **MUST ONLY** use the Diagnosis Interface VAS 6154 (WiFi Diagnostic Tool) in USB OPERATION or the CABLE-CONNECTED VAS 5055 for the reprogramming (updating) of the control units.

- If neither of these units are available, the VAS 5054 (A) may be used in USB MODE.
- **DO NOT** under any circumstances use a Bluetooth connection to conduct the reprogramming (updating) of any control units.

Battery Charger



CAUTION

ONLY Chargers that meet the approved specification on the Mandatory Equipment List (available on the Bentley Hub) **MUST** be used.

- The charger must be set to a mode where a **MINIMUM** of 90a is supplied to the battery during the process. Typically, this is known as ‘Power Supply Mode’ or ‘DIAG+ Mode’.
- A voltage of exactly 14.8v must be set and maintained throughout the process.
- Please refer to the manual to ensure that these requirements are met before beginning any SVM update

Preparation Before Update



WARNING

Hybrid Vehicles use a High Voltage System and therefore **MUST ONLY** be worked on by suitable personnel.




CAUTION

During the update, switch off all unnecessary consumers. For example, ventilation, seat heaters, interior illumination, exterior lights ect.

Firstly, conduct a full guided fault find of the vehicle.

If a 'Check Installation List' pop-up appears, select 'close' (see below image)



Referring to TPI 2075920, address any unknown faults **BEFORE** conducting any of the below updates.

Ensure that the correct battery charge is connected to the vehicle. – Refer to the “Battery Charger” Section above.

Obtaining Flash files for ODIS-S

Visit <https://bentley.atheer.io/> and log in with the following case-sensitive account details.

- Username: bilupdate
- Password: Bentley123!



NOTICE

If you are already logged into your retailer account, you will need to logout first. To do this, click on your account initials (bottom left corner) and click “Sign Out”.

After logging in, using the navigation bar on the left hand side, click on the ‘conversations’ tab



Next, click the conversation named “ED40 Campaign”

In this conversation, you will find a file named “ED40_Local_Flash_Files”. Left click the file name and download the file.

Left click the file name and download the folder.

After left-clicking the files to download them, the download will take circa 5-10 minutes, do not interrupt this process. You may need to wait a short period (internet speed dependent) for the files to download.

During/before the download commences, there may be a warning about a "pop-up" being blocked which will prevent the file from downloading, ensure to select option "Allow Pop-Ups from this website" to download the file. Wording may differ depending on web browser.

Locate the download file and extract it. To do this, right click the file, click “7 zip” and then “Extract here”

After successfully downloading the file, please logout of the account.

Downloading Flash Files for ODIS-S

From the content within the ‘ED40_Local_Flash_Files’ download, copy the content of the folder into your root c:/temp drive on your ODIS device.

- FL_4M0915249AN_0201_UPD0004T0005_V001_S.odx
- FL_4M0915249AM_0207_ABJB7A60590M1_V001_S.odx
- FL_4M0915231AH_0204_XHX15EV0421M6_V001_S.odx

Obtaining Correct SVM Code

Due to the intricacies behind Bentley Integration Levels (BiL), you must identify which SVM code each VIN requires.

Please find the applicable VIN on the attached “ed37_svm_code” document.

Note down the associated SVM code from the SVM Code column.

Keep note of this SVM code as you will be required to enter this into ODIS-S, later on in the procedure.

First SVM Code Input



CAUTION

At this point, a suitable battery charger must be connected to the vehicle.

1. In ODIS-S, navigate to the “Special Functions” tab.
2. Navigate to ‘SVM – Code Input’ and enter the SVM code which you have obtained from the attached “ed37_svm_code” pdf.
3. On the next screen, ensure that the SVM code displayed is correct.
4. You will be shown the communication type. **This MUST be set to “DoIP”.**
 - a. If “DoIP” is not selected, select option 3 until the communication type is set to “DoIP”.
5. After ensuring DoIP is selected, and a suitable battery charger is connected, select Option 1 – “Yes”.
 - a. From here, all control modules will be interrogated and the SVM action will take place.
6. Ensure that the diagnostic device remains connected for the duration of the update.
7. Follow all on-screen prompts until the program ends.
 - a. If you have a prompt stating there is no communication established with 00CC, select done/continue.
8. Follow the on-screen instructions to completion.
9. Perform a 15 minute CAN bus sleep.
 - a. Turn off the ignition.
 - b. Remove all equipment from the car (Diagnostic tester/dongle, battery charger, keys).
 - c. Close all doors, windows, bonnet and boot lid.
 - d. Lock the vehicle to perform a CAN-BUS sleep (wait 15 minutes).
10. Perform a whole vehicle DTC clear by exiting the current diagnostic session.
11. Re-run guided fault finding and clear DTCs.

High Voltage Shutdown




WARNING

De-energise the high-voltage system via ODIS-S. Refer to ElsaPro, Repair Group 93 – “De-energising high-voltage system” to do so.

1. After de-energisation, Refer to ElsaPro Repair Group 70 ‘Boot carpet – To remove and fit’. Remove the boot floor and gain access to the earth cable from the 12v battery negative and the body in white (This access will be required later in the test plan).

2. Navigate to 'Special functions' and select 'SVM – Pre 372BIL5201 Hotfix Routines', then 'Perform test'.
3. Switch to 'DoIP' when prompted.
4. Select option 8) BMC/BJB 204/207 Update Repair' and follow the on-screen instructions.
 - When the tester attempts to flash '008C - Battery regulation control module' you may receive a message informing you that the preconditions have not been met. Select 'done/continue'.
 - On the following screen (shown below) select option 2 to attempt to flash the ECU – this should allow the '008C - Battery regulation control module' to flash successfully.



NOTICE

If the flash fails, perform the below actions.

1. Exit the test.
2. Allow the car to sleep for 5 minutes.
 - a. Turn off the ignition.
 - b. Remove all equipment from the car (Diagnostic tester/dongle, battery charger, keys).
 - c. Close all doors, windows, bonnet and boot lid.
 - d. Lock the vehicle to perform a CAN-BUS sleep (wait 5 minutes).
3. Clear DTCs from '008C - Battery regulation control module'.
 - 3a. To do this, right click on control unit 008C, click Guided Functions and then click 'Clear Fault Memory'.

4. Return to 'Special functions' and run the test plan 'SVM – Pre 372BIL5201 Hotfix Routines'.
5. Within this test plan, select option 5 (008C BCM - Restore Communications with BJB) and run until completion.
6. Once the test has been completed, right click on control unit 008C and select guided functions. Then, read ECU Identification and ensure that the 06D0 (Battery Junction Box) appears as a subsystem within the read identification test plan.
7. Continue to the next SVM update.

Second SVM Code Input




WARNING

Re-energise the high-voltage system via ODIS-S. Refer to ElsaPro, Repair Group 93 – “Re-energising high-voltage system” to do so.

1. After re-energising the High Voltage system, navigate to the “Special Functions” tab in ODIS-S.
2. Navigate to 'SVM – Code Input'
 - a. If the vehicle is any variant of a Continental GT or GTC, enter the SVM Code: “372531COM01”.
 - b. If the vehicle is any variant of a Continental Flying Spur, enter the SVM Code: “373531COM02”.
3. On the next screen, ensure that the SVM code displayed is correct.
4. You will be shown the communication type. **This MUST be set to “DoIP”.**
 - a. If “DoIP” is not selected, select option 3 until the communication type is set to “DoIP”.
5. After ensuring DoIP is selected, and a suitable battery charger is connected, select Option 1 – “Yes”.
 - a. From here, all control modules will be interrogated and the SVM action will take place.
6. Ensure that the diagnostic device remains connected for the duration of the update.
7. Follow all on-screen prompts until the program ends.
 - a. If you have a prompt stating there is no communication established with 00CC, select done/continue.

8. Follow the on-screen instructions to completion.

9. If you are presented with this screen at the end of the update, the update was successful. Please continue to step 11.



10. If you encounter any errors during the update, please raise a FULL TECHNICAL DISS query.

a. Customer Statement: "ED37 Support"

b. Workshop Findings: Give a summary of the error encountered and ensure that the GFF log is submitted online.

11. After successful completion of the update, perform the following.

a. Turn off the ignition.

b. Remove all equipment from the car (Diagnostic tester/dongle, battery charger, keys).

c. Close all doors, windows, bonnet and boot lid.

d. Lock the vehicle to perform a CAN-BUS sleep (wait 10 minutes).

12. After 30 minutes, unlock and open the driver's door. Turn on the ignition, re-connect the battery charger and diagnostic dongle.

13. Re-run guided fault finding and clear DTCs. If any faults are present, refer to TPI 2075920. If any other faults are present are non-sporadic, please raise a full DISS query with a full GFF log uploaded online stating the error encountered.

Identification

Once the applicable action has been conducted, the operative must submit a warranty claim as this will show the service campaign action as complete within Elsa Pro “Repair history”.

You must also add a yellow paint mark as per the picture below.



 [Repair instructions](#)  [Notes](#)

VIN	SVM Code
SCBCJ13S2SC021160	372531ED3701
SCBCJ13S3SC021233	372531ED3701
SCBCR2ZG0SC017898	372531ED3701
SCBCR2ZG0SC018114	372531ED3701
SCBCR2ZG0SC018128	372531ED3701
SCBCR2ZG0SC018131	372531ED3701
SCBCR2ZG0SC018145	372531ED3701
SCBCR2ZG0SC018159	372531ED3701
SCBCR2ZG0SC018162	372531ED3701
SCBCR2ZG0SC019974	372531ED3701
SCBCR2ZG0SC020042	372531ED3701
SCBCR2ZG0SC020087	372531ED3701
SCBCR2ZG0SC020123	372531ED3701
SCBCR2ZG0SC020154	372531ED3701
SCBCR2ZG0SC020168	372531ED3701
SCBCR2ZG0SC020185	372531ED3701
SCBCR2ZG0SC020218	372531ED3701
SCBCR2ZG0SC020266	372531ED3701
SCBCR2ZG0SC020347	372531ED3701
SCBCR2ZG0SC020610	372531ED3701
SCBCR2ZG0SC020803	372531ED3701
SCBCR2ZG0SC021143	372531ED3701
SCBCR2ZG0SC021174	372531ED3701
SCBCR2ZG0SC021207	372531ED3701
SCBCR2ZG1SC018123	372531ED3701
SCBCR2ZG1SC018137	372531ED3701
SCBCR2ZG1SC018140	372531ED3701
SCBCR2ZG1SC018154	372531ED3701
SCBCR2ZG1SC018168	372531ED3701
SCBCR2ZG1SC019904	372531ED3701
SCBCR2ZG1SC020003	372531ED3701
SCBCR2ZG1SC020051	372531ED3701
SCBCR2ZG1SC020082	372531ED3701
SCBCR2ZG1SC020101	372531ED3701
SCBCR2ZG1SC020244	372531ED3701
SCBCR2ZG1SC020857	372531ED3701
SCBCR2ZG1SC020938	372531ED3701
SCBCR2ZG1SC021023	372531ED3701
SCBCR2ZG1SC021149	372531ED3701
SCBCR2ZG1SC021152	372531ED3701
SCBCR2ZG1SC021166	372531ED3701
SCBCR2ZG1SC021197	372531ED3701
SCBCR2ZG1SC021250	372531ED3701
SCBCR2ZG2SC018020	372531ED3701
SCBCR2ZG2SC018115	372531ED3701

SCBCR2ZG2SC018129	372531ED3701
SCBCR2ZG2SC018132	372531ED3701
SCBCR2ZG2SC018146	372531ED3701
SCBCR2ZG2SC018163	372531ED3701
SCBCR2ZG2SC019913	372531ED3701
SCBCR2ZG2SC019958	372531ED3701
SCBCR2ZG2SC020009	372531ED3701
SCBCR2ZG2SC020012	372531ED3701
SCBCR2ZG2SC020060	372531ED3701
SCBCR2ZG2SC020088	372531ED3701
SCBCR2ZG2SC020107	372531ED3701
SCBCR2ZG2SC020155	372531ED3701
SCBCR2ZG2SC020284	372531ED3701
SCBCR2ZG2SC020298	372531ED3701
SCBCR2ZG2SC020866	372531ED3701
SCBCR2ZG2SC021063	372531ED3701
SCBCR2ZG2SC021127	372531ED3701
SCBCR2ZG2SC021158	372531ED3701
SCBCR2ZG2SC021225	372531ED3701
SCBCR2ZG2SC021242	372531ED3701
SCBCR2ZG3SC018124	372531ED3701
SCBCR2ZG3SC018138	372531ED3701
SCBCR2ZG3SC018141	372531ED3701
SCBCR2ZG3SC018155	372531ED3701
SCBCR2ZG3SC018169	372531ED3701
SCBCR2ZG3SC019922	372531ED3701
SCBCR2ZG3SC019984	372531ED3701
SCBCR2ZG3SC019998	372531ED3701
SCBCR2ZG3SC020035	372531ED3701
SCBCR2ZG3SC020049	372531ED3701
SCBCR2ZG3SC020097	372531ED3701
SCBCR2ZG3SC020116	372531ED3701
SCBCR2ZG3SC020424	372531ED3701
SCBCR2ZG3SC020438	372531ED3701
SCBCR2ZG3SC020505	372531ED3701
SCBCR2ZG3SC020567	372531ED3701
SCBCR2ZG4SC018021	372531ED3701
SCBCR2ZG4SC018116	372531ED3701
SCBCR2ZG4SC018133	372531ED3701
SCBCR2ZG4SC018147	372531ED3701
SCBCR2ZG4SC018150	372531ED3701
SCBCR2ZG4SC018164	372531ED3701
SCBCR2ZG4SC019900	372531ED3701
SCBCR2ZG4SC019914	372531ED3701
SCBCR2ZG4SC019928	372531ED3701
SCBCR2ZG4SC019945	372531ED3701

SCBCR2ZG4SC019976	372531ED3701
SCBCR2ZG4SC019993	372531ED3701
SCBCR2ZG4SC020027	372531ED3701
SCBCR2ZG4SC020058	372531ED3701
SCBCR2ZG4SC020108	372531ED3701
SCBCR2ZG4SC020139	372531ED3701
SCBCR2ZG4SC020142	372531ED3701
SCBCR2ZG4SC020190	372531ED3701
SCBCR2ZG4SC020318	372531ED3701
SCBCR2ZG4SC020383	372531ED3701
SCBCR2ZG4SC020478	372531ED3701
SCBCR2ZG4SC020531	372531ED3701
SCBCR2ZG4SC020710	372531ED3701
SCBCR2ZG4SC021114	372531ED3701
SCBCR2ZG4SC021193	372531ED3701
SCBCR2ZG5SC018125	372531ED3701
SCBCR2ZG5SC018139	372531ED3701
SCBCR2ZG5SC018142	372531ED3701
SCBCR2ZG5SC018156	372531ED3701
SCBCR2ZG5SC019968	372531ED3701
SCBCR2ZG5SC019971	372531ED3701
SCBCR2ZG5SC020022	372531ED3701
SCBCR2ZG5SC020053	372531ED3701
SCBCR2ZG5SC020067	372531ED3701
SCBCR2ZG5SC020103	372531ED3701
SCBCR2ZG5SC020134	372531ED3701
SCBCR2ZG5SC020148	372531ED3701
SCBCR2ZG5SC020165	372531ED3701
SCBCR2ZG5SC020182	372531ED3701
SCBCR2ZG5SC020683	372531ED3701
SCBCR2ZG5SC020828	372531ED3701
SCBCR2ZG5SC020912	372531ED3701
SCBCR2ZG5SC020943	372531ED3701
SCBCR2ZG5SC020991	372531ED3701
SCBCR2ZG5SC021042	372531ED3701
SCBCR2ZG5SC021137	372531ED3701
SCBCR2ZG6SC018117	372531ED3701
SCBCR2ZG6SC018120	372531ED3701
SCBCR2ZG6SC018134	372531ED3701
SCBCR2ZG6SC018148	372531ED3701
SCBCR2ZG6SC018151	372531ED3701
SCBCR2ZG6SC018165	372531ED3701
SCBCR2ZG6SC019963	372531ED3701
SCBCR2ZG6SC020014	372531ED3701
SCBCR2ZG6SC020031	372531ED3701
SCBCR2ZG6SC020076	372531ED3701

SCBCR2ZG6SC020093	372531ED3701
SCBCR2ZG6SC020174	372531ED3701
SCBCR2ZG6SC020269	372531ED3701
SCBCR2ZG6SC020336	372531ED3701
SCBCR2ZG6SC020515	372531ED3701
SCBCR2ZG6SC020952	372531ED3701
SCBCR2ZG6SC021020	372531ED3701
SCBCR2ZG6SC021101	372531ED3701
SCBCR2ZG6SC021129	372531ED3701
SCBCR2ZG6SC021227	372531ED3701
SCBCR2ZG7SC018126	372531ED3701
SCBCR2ZG7SC018157	372531ED3701
SCBCR2ZG7SC018160	372531ED3701
SCBCR2ZG7SC019910	372531ED3701
SCBCR2ZG7SC019938	372531ED3701
SCBCR2ZG7SC019955	372531ED3701
SCBCR2ZG7SC020006	372531ED3701
SCBCR2ZG7SC020121	372531ED3701
SCBCR2ZG7SC020152	372531ED3701
SCBCR2ZG7SC020300	372531ED3701
SCBCR2ZG7SC020555	372531ED3701
SCBCR2ZG7SC020619	372531ED3701
SCBCR2ZG7SC020782	372531ED3701
SCBCR2ZG7SC020863	372531ED3701
SCBCR2ZG7SC020927	372531ED3701
SCBCR2ZG7SC020944	372531ED3701
SCBCR2ZG7SC020992	372531ED3701
SCBCR2ZG7SC021043	372531ED3701
SCBCR2ZG7SC021091	372531ED3701
SCBCR2ZG7SC021141	372531ED3701
SCBCR2ZG8SC018118	372531ED3701
SCBCR2ZG8SC018121	372531ED3701
SCBCR2ZG8SC018135	372531ED3701
SCBCR2ZG8SC018149	372531ED3701
SCBCR2ZG8SC018152	372531ED3701
SCBCR2ZG8SC018166	372531ED3701
SCBCR2ZG8SC019933	372531ED3701
SCBCR2ZG8SC020001	372531ED3701
SCBCR2ZG8SC020015	372531ED3701
SCBCR2ZG8SC020063	372531ED3701
SCBCR2ZG8SC020127	372531ED3701
SCBCR2ZG8SC020192	372531ED3701
SCBCR2ZG8SC020256	372531ED3701
SCBCR2ZG8SC020306	372531ED3701
SCBCR2ZG8SC020452	372531ED3701
SCBCR2ZG8SC020838	372531ED3701

SCBCR2ZG8SC020967	372531ED3701
SCBCR2ZG8SC021004	372531ED3701
SCBCR2ZG8SC021035	372531ED3701
SCBCR2ZG8SC021116	372531ED3701
SCBCR2ZG8SC021164	372531ED3701
SCBCR2ZG8SC021181	372531ED3701
SCBCR2ZG9SC018113	372531ED3701
SCBCR2ZG9SC018127	372531ED3701
SCBCR2ZG9SC018130	372531ED3701
SCBCR2ZG9SC018144	372531ED3701
SCBCR2ZG9SC018158	372531ED3701
SCBCR2ZG9SC018161	372531ED3701
SCBCR2ZG9SC019908	372531ED3701
SCBCR2ZG9SC019939	372531ED3701
SCBCR2ZG9SC019942	372531ED3701
SCBCR2ZG9SC019987	372531ED3701
SCBCR2ZG9SC019990	372531ED3701
SCBCR2ZG9SC020038	372531ED3701
SCBCR2ZG9SC020069	372531ED3701
SCBCR2ZG9SC020072	372531ED3701
SCBCR2ZG9SC020119	372531ED3701
SCBCR2ZG9SC020170	372531ED3701
SCBCR2ZG9SC020489	372531ED3701
SCBCR2ZG9SC020525	372531ED3701
SCBCR2ZG9SC021030	372531ED3701
SCBCR2ZG9SC021058	372531ED3701
SCBCR2ZG9SC021173	372531ED3701
SCBCR2ZGXSC018119	372531ED3701
SCBCR2ZGXSC018122	372531ED3701
SCBCR2ZGXSC018136	372531ED3701
SCBCR2ZGXSC018153	372531ED3701
SCBCR2ZGXSC018167	372531ED3701
SCBCR2ZGXSC019948	372531ED3701
SCBCR2ZGXSC019951	372531ED3701
SCBCR2ZGXSC019979	372531ED3701
SCBCR2ZGXSC020081	372531ED3701
SCBCR2ZGXSC020100	372531ED3701
SCBCR2ZGXSC020114	372531ED3701
SCBCR2ZGXSC020131	372531ED3701
SCBCR2ZGXSC020145	372531ED3701
SCBCR2ZGXSC020162	372531ED3701
SCBCR2ZGXSC020193	372531ED3701
SCBCR2ZGXSC020470	372531ED3701
SCBCR2ZGXSC020484	372531ED3701
SCBCR2ZGXSC020579	372531ED3701
SCBCR2ZGXSC020825	372531ED3701

SCBCR2ZGXSC020890	372531ED3701
SCBCR2ZGXSC020954	372531ED3701
SCBCR2ZGXSC021067	372531ED3701
SCBCR2ZGXSC021070	372531ED3701
SCBCR2ZGXSC021134	372531ED3701
SCBCR2ZGXSC021215	372531ED3701
SCBDR4ZG0SC019912	372531ED3701
SCBDR4ZG0SC019991	372531ED3701
SCBDR4ZG0SC020011	372531ED3701
SCBDR4ZG0SC020073	372531ED3701
SCBDR4ZG0SC020106	372531ED3701
SCBDR4ZG0SC020199	372531ED3701
SCBDR4ZG0SC020221	372531ED3701
SCBDR4ZG0SC020297	372531ED3701
SCBDR4ZG0SC020509	372531ED3701
SCBDR4ZG0SC020641	372531ED3701
SCBDR4ZG0SC020669	372531ED3701
SCBDR4ZG0SC020865	372531ED3701
SCBDR4ZG0SC021188	372531ED3701
SCBDR4ZG1SC019935	372531ED3701
SCBDR4ZG1SC019949	372531ED3701
SCBDR4ZG1SC019983	372531ED3701
SCBDR4ZG1SC019997	372531ED3701
SCBDR4ZG1SC020048	372531ED3701
SCBDR4ZG1SC020065	372531ED3701
SCBDR4ZG1SC020096	372531ED3701
SCBDR4ZG1SC020115	372531ED3701
SCBDR4ZG1SC020129	372531ED3701
SCBDR4ZG1SC020132	372531ED3701
SCBDR4ZG1SC020180	372531ED3701
SCBDR4ZG1SC020194	372531ED3701
SCBDR4ZG1SC020213	372531ED3701
SCBDR4ZG1SC020230	372531ED3701
SCBDR4ZG1SC020289	372531ED3701
SCBDR4ZG1SC020499	372531ED3701
SCBDR4ZG1SC020731	372531ED3701
SCBDR4ZG1SC020812	372531ED3701
SCBDR4ZG1SC020874	372531ED3701
SCBDR4ZG1SC020888	372531ED3701
SCBDR4ZG1SC020972	372531ED3701
SCBDR4ZG1SC021040	372531ED3701
SCBDR4ZG1SC021121	372531ED3701
SCBDR4ZG2SC019975	372531ED3701
SCBDR4ZG2SC020026	372531ED3701
SCBDR4ZG2SC020043	372531ED3701
SCBDR4ZG2SC020124	372531ED3701

SCBDR4ZG2SC020138	372531ED3701
SCBDR4ZG2SC020141	372531ED3701
SCBDR4ZG2SC020169	372531ED3701
SCBDR4ZG2SC020172	372531ED3701
SCBDR4ZG2SC020186	372531ED3701
SCBDR4ZG2SC020253	372531ED3701
SCBDR4ZG2SC020334	372531ED3701
SCBDR4ZG2SC020365	372531ED3701
SCBDR4ZG2SC020415	372531ED3701
SCBDR4ZG2SC020530	372531ED3701
SCBDR4ZG2SC020575	372531ED3701
SCBDR4ZG2SC020849	372531ED3701
SCBDR4ZG2SC020852	372531ED3701
SCBDR4ZG2SC020883	372531ED3701
SCBDR4ZG2SC021094	372531ED3701
SCBDR4ZG2SC021161	372531ED3701
SCBDR4ZG2SC021192	372531ED3701
SCBDR4ZG3SC019953	372531ED3701
SCBDR4ZG3SC020021	372531ED3701
SCBDR4ZG3SC020052	372531ED3701
SCBDR4ZG3SC020083	372531ED3701
SCBDR4ZG3SC020102	372531ED3701
SCBDR4ZG3SC020147	372531ED3701
SCBDR4ZG3SC020150	372531ED3701
SCBDR4ZG3SC020164	372531ED3701
SCBDR4ZG3SC020228	372531ED3701
SCBDR4ZG3SC020245	372531ED3701
SCBDR4ZG3SC020598	372531ED3701
SCBDR4ZG3SC020794	372531ED3701
SCBDR4ZG3SC020844	372531ED3701
SCBDR4ZG3SC021136	372531ED3701
SCBDR4ZG3SC021170	372531ED3701
SCBDR4ZG3SC021248	372531ED3701
SCBDR4ZG4SC019962	372531ED3701
SCBDR4ZG4SC020075	372531ED3701
SCBDR4ZG4SC020089	372531ED3701
SCBDR4ZG4SC020092	372531ED3701
SCBDR4ZG4SC020156	372531ED3701
SCBDR4ZG4SC020223	372531ED3701
SCBDR4ZG4SC020299	372531ED3701
SCBDR4ZG4SC020559	372531ED3701
SCBDR4ZG4SC020755	372531ED3701
SCBDR4ZG4SC020822	372531ED3701
SCBDR4ZG4SC020836	372531ED3701
SCBDR4ZG4SC021226	372531ED3701
SCBDR4ZG4SC021243	372531ED3701

SCBDR4ZG5SC019906	372531ED3701
SCBDR4ZG5SC019923	372531ED3701
SCBDR4ZG5SC019937	372531ED3701
SCBDR4ZG5SC020005	372531ED3701
SCBDR4ZG5SC020120	372531ED3701
SCBDR4ZG5SC020196	372531ED3701
SCBDR4ZG5SC020215	372531ED3701
SCBDR4ZG5SC020294	372531ED3701
SCBDR4ZG5SC020313	372531ED3701
SCBDR4ZG5SC020344	372531ED3701
SCBDR4ZG5SC020389	372531ED3701
SCBDR4ZG5SC020635	372531ED3701
SCBDR4ZG5SC020859	372531ED3701
SCBDR4ZG5SC020862	372531ED3701
SCBDR4ZG5SC020893	372531ED3701
SCBDR4ZG5SC020909	372531ED3701
SCBDR4ZG5SC021123	372531ED3701
SCBDR4ZG5SC021140	372531ED3701
SCBDR4ZG5SC021154	372531ED3701
SCBDR4ZG5SC021218	372531ED3701
SCBDR4ZG6SC019929	372531ED3701
SCBDR4ZG6SC019932	372531ED3701
SCBDR4ZG6SC019946	372531ED3701
SCBDR4ZG6SC019977	372531ED3701
SCBDR4ZG6SC019980	372531ED3701
SCBDR4ZG6SC019994	372531ED3701
SCBDR4ZG6SC020000	372531ED3701
SCBDR4ZG6SC020045	372531ED3701
SCBDR4ZG6SC020059	372531ED3701
SCBDR4ZG6SC020062	372531ED3701
SCBDR4ZG6SC020112	372531ED3701
SCBDR4ZG6SC020126	372531ED3701
SCBDR4ZG6SC020238	372531ED3701
SCBDR4ZG6SC020255	372531ED3701
SCBDR4ZG6SC020451	372531ED3701
SCBDR4ZG6SC020580	372531ED3701
SCBDR4ZG6SC020630	372531ED3701
SCBDR4ZG6SC020658	372531ED3701
SCBDR4ZG6SC020806	372531ED3701
SCBDR4ZG6SC020871	372531ED3701
SCBDR4ZG6SC020899	372531ED3701
SCBDR4ZG6SC021034	372531ED3701
SCBDR4ZG6SC021177	372531ED3701
SCBDR4ZG6SC021194	372531ED3701
SCBDR4ZG7SC019941	372531ED3701
SCBDR4ZG7SC019969	372531ED3701

SCBDR4ZG7SC019972	372531ED3701
SCBDR4ZG7SC019986	372531ED3701
SCBDR4ZG7SC020037	372531ED3701
SCBDR4ZG7SC020068	372531ED3701
SCBDR4ZG7SC020071	372531ED3701
SCBDR4ZG7SC020099	372531ED3701
SCBDR4ZG7SC020118	372531ED3701
SCBDR4ZG7SC020183	372531ED3701
SCBDR4ZG7SC020233	372531ED3701
SCBDR4ZG7SC020278	372531ED3701
SCBDR4ZG7SC020281	372531ED3701
SCBDR4ZG7SC020328	372531ED3701
SCBDR4ZG7SC020362	372531ED3701
SCBDR4ZG7SC020538	372531ED3701
SCBDR4ZG7SC020569	372531ED3701
SCBDR4ZG7SC020751	372531ED3701
SCBDR4ZG7SC020796	372531ED3701
SCBDR4ZG7SC020801	372531ED3701
SCBDR4ZG7SC020815	372531ED3701
SCBDR4ZG7SC020913	372531ED3701
SCBDR4ZG7SC021172	372531ED3701
SCBDR4ZG8SC019902	372531ED3701
SCBDR4ZG8SC020029	372531ED3701
SCBDR4ZG8SC020080	372531ED3701
SCBDR4ZG8SC020094	372531ED3701
SCBDR4ZG8SC020144	372531ED3701
SCBDR4ZG8SC020158	372531ED3701
SCBDR4ZG8SC020161	372531ED3701
SCBDR4ZG8SC020175	372531ED3701
SCBDR4ZG8SC020189	372531ED3701
SCBDR4ZG8SC020208	372531ED3701
SCBDR4ZG8SC020225	372531ED3701
SCBDR4ZG8SC020242	372531ED3701
SCBDR4ZG8SC020645	372531ED3701
SCBDR4ZG8SC020869	372531ED3701
SCBDR4ZG8SC020922	372531ED3701
SCBDR4ZG8SC021214	372531ED3701
SCBDR4ZG8SC021228	372531ED3701
SCBDR4ZG8SC021231	372531ED3701
SCBDR4ZG9SC019956	372531ED3701
SCBDR4ZG9SC020007	372531ED3701
SCBDR4ZG9SC020024	372531ED3701
SCBDR4ZG9SC020041	372531ED3701
SCBDR4ZG9SC020086	372531ED3701
SCBDR4ZG9SC020136	372531ED3701
SCBDR4ZG9SC020153	372531ED3701

SCBDR4ZG9SC020167	372531ED3701
SCBDR4ZG9SC020251	372531ED3701
SCBDR4ZG9SC020301	372531ED3701
SCBDR4ZG9SC020332	372531ED3701
SCBDR4ZG9SC020413	372531ED3701
SCBDR4ZG9SC020461	372531ED3701
SCBDR4ZG9SC020492	372531ED3701
SCBDR4ZG9SC020573	372531ED3701
SCBDR4ZG9SC020587	372531ED3701
SCBDR4ZG9SC020590	372531ED3701
SCBDR4ZG9SC020606	372531ED3701
SCBDR4ZG9SC020721	372531ED3701
SCBDR4ZG9SC020833	372531ED3701
SCBDR4ZG9SC021125	372531ED3701
SCBDR4ZG9SC021142	372531ED3701
SCBDR4ZG9SC021223	372531ED3701
SCBDR4ZGXSC019898	372531ED3701
SCBDR4ZGXSC019920	372531ED3701
SCBDR4ZGXSC019965	372531ED3701
SCBDR4ZGXSC020016	372531ED3701
SCBDR4ZGXSC020033	372531ED3701
SCBDR4ZGXSC020078	372531ED3701
SCBDR4ZGXSC020274	372531ED3701
SCBDR4ZGXSC020291	372531ED3701
SCBDR4ZGXSC020324	372531ED3701
SCBDR4ZGXSC020338	372531ED3701
SCBDR4ZGXSC020808	372531ED3701
SCBDR4ZGXSC021179	372531ED3701
SCBDR4ZGXSC021182	372531ED3701
SCBDR4ZGXSC021201	372531ED3701
SCBDR4ZGXSC021246	372531ED3701
SCBCJ13S9SC021236	372531ED3701

SCBCJ13S2SC021160	SCBCR2ZG1SC020051	SCBCR2ZG2SC021158
SCBCJ13S3SC021233	SCBCR2ZG1SC020082	SCBCR2ZG2SC021225
SCBCR2ZG0SC017898	SCBCR2ZG1SC020101	SCBCR2ZG2SC021242
SCBCR2ZG0SC018114	SCBCR2ZG1SC020244	SCBCR2ZG3SC018124
SCBCR2ZG0SC018128	SCBCR2ZG1SC020857	SCBCR2ZG3SC018138
SCBCR2ZG0SC018131	SCBCR2ZG1SC020938	SCBCR2ZG3SC018141
SCBCR2ZG0SC018145	SCBCR2ZG1SC021023	SCBCR2ZG3SC018155
SCBCR2ZG0SC018159	SCBCR2ZG1SC021149	SCBCR2ZG3SC018169
SCBCR2ZG0SC018162	SCBCR2ZG1SC021152	SCBCR2ZG3SC019922
SCBCR2ZG0SC019974	SCBCR2ZG1SC021166	SCBCR2ZG3SC019984
SCBCR2ZG0SC020042	SCBCR2ZG1SC021197	SCBCR2ZG3SC019998
SCBCR2ZG0SC020087	SCBCR2ZG1SC021250	SCBCR2ZG3SC020035
SCBCR2ZG0SC020123	SCBCR2ZG2SC018020	SCBCR2ZG3SC020049
SCBCR2ZG0SC020154	SCBCR2ZG2SC018115	SCBCR2ZG3SC020097
SCBCR2ZG0SC020168	SCBCR2ZG2SC018129	SCBCR2ZG3SC020116
SCBCR2ZG0SC020185	SCBCR2ZG2SC018132	SCBCR2ZG3SC020424
SCBCR2ZG0SC020218	SCBCR2ZG2SC018146	SCBCR2ZG3SC020438
SCBCR2ZG0SC020266	SCBCR2ZG2SC018163	SCBCR2ZG3SC020505
SCBCR2ZG0SC020347	SCBCR2ZG2SC019913	SCBCR2ZG3SC020567
SCBCR2ZG0SC020610	SCBCR2ZG2SC019958	SCBCR2ZG4SC018021
SCBCR2ZG0SC020803	SCBCR2ZG2SC020009	SCBCR2ZG4SC018116
SCBCR2ZG0SC021143	SCBCR2ZG2SC020012	SCBCR2ZG4SC018133
SCBCR2ZG0SC021174	SCBCR2ZG2SC020060	SCBCR2ZG4SC018147
SCBCR2ZG0SC021207	SCBCR2ZG2SC020088	SCBCR2ZG4SC018150
SCBCR2ZG1SC018123	SCBCR2ZG2SC020107	SCBCR2ZG4SC018164
SCBCR2ZG1SC018137	SCBCR2ZG2SC020155	SCBCR2ZG4SC019900
SCBCR2ZG1SC018140	SCBCR2ZG2SC020284	SCBCR2ZG4SC019914
SCBCR2ZG1SC018154	SCBCR2ZG2SC020298	SCBCR2ZG4SC019928
SCBCR2ZG1SC018168	SCBCR2ZG2SC020866	SCBCR2ZG4SC019945
SCBCR2ZG1SC019904	SCBCR2ZG2SC021063	SCBCR2ZG4SC019976
SCBCR2ZG1SC020003	SCBCR2ZG2SC021127	SCBCR2ZG4SC019993

SCBCR2ZG4SC020027	SCBCR2ZG5SC020991	SCBCR2ZG7SC020152
SCBCR2ZG4SC020058	SCBCR2ZG5SC021042	SCBCR2ZG7SC020300
SCBCR2ZG4SC020108	SCBCR2ZG5SC021137	SCBCR2ZG7SC020555
SCBCR2ZG4SC020139	SCBCR2ZG6SC018117	SCBCR2ZG7SC020619
SCBCR2ZG4SC020142	SCBCR2ZG6SC018120	SCBCR2ZG7SC020782
SCBCR2ZG4SC020190	SCBCR2ZG6SC018134	SCBCR2ZG7SC020863
SCBCR2ZG4SC020318	SCBCR2ZG6SC018148	SCBCR2ZG7SC020927
SCBCR2ZG4SC020383	SCBCR2ZG6SC018151	SCBCR2ZG7SC020944
SCBCR2ZG4SC020478	SCBCR2ZG6SC018165	SCBCR2ZG7SC020992
SCBCR2ZG4SC020531	SCBCR2ZG6SC019963	SCBCR2ZG7SC021043
SCBCR2ZG4SC020710	SCBCR2ZG6SC020014	SCBCR2ZG7SC021091
SCBCR2ZG4SC021114	SCBCR2ZG6SC020031	SCBCR2ZG7SC021141
SCBCR2ZG4SC021193	SCBCR2ZG6SC020076	SCBCR2ZG8SC018118
SCBCR2ZG5SC018125	SCBCR2ZG6SC020093	SCBCR2ZG8SC018121
SCBCR2ZG5SC018139	SCBCR2ZG6SC020174	SCBCR2ZG8SC018135
SCBCR2ZG5SC018142	SCBCR2ZG6SC020269	SCBCR2ZG8SC018149
SCBCR2ZG5SC018156	SCBCR2ZG6SC020336	SCBCR2ZG8SC018152
SCBCR2ZG5SC019968	SCBCR2ZG6SC020515	SCBCR2ZG8SC018166
SCBCR2ZG5SC019971	SCBCR2ZG6SC020952	SCBCR2ZG8SC019933
SCBCR2ZG5SC020022	SCBCR2ZG6SC021020	SCBCR2ZG8SC020001
SCBCR2ZG5SC020053	SCBCR2ZG6SC021101	SCBCR2ZG8SC020015
SCBCR2ZG5SC020067	SCBCR2ZG6SC021129	SCBCR2ZG8SC020063
SCBCR2ZG5SC020103	SCBCR2ZG6SC021227	SCBCR2ZG8SC020127
SCBCR2ZG5SC020134	SCBCR2ZG7SC018126	SCBCR2ZG8SC020192
SCBCR2ZG5SC020148	SCBCR2ZG7SC018157	SCBCR2ZG8SC020256
SCBCR2ZG5SC020165	SCBCR2ZG7SC018160	SCBCR2ZG8SC020306
SCBCR2ZG5SC020182	SCBCR2ZG7SC019910	SCBCR2ZG8SC020452
SCBCR2ZG5SC020683	SCBCR2ZG7SC019938	SCBCR2ZG8SC020838
SCBCR2ZG5SC020828	SCBCR2ZG7SC019955	SCBCR2ZG8SC020967
SCBCR2ZG5SC020912	SCBCR2ZG7SC020006	SCBCR2ZG8SC021004
SCBCR2ZG5SC020943	SCBCR2ZG7SC020121	SCBCR2ZG8SC021035

SCBCR2ZG8SC021116	SCBCR2ZGXSC019979	SCBDR4ZG1SC019935
SCBCR2ZG8SC021164	SCBCR2ZGXSC020081	SCBDR4ZG1SC019949
SCBCR2ZG8SC021181	SCBCR2ZGXSC020100	SCBDR4ZG1SC019983
SCBCR2ZG9SC018113	SCBCR2ZGXSC020114	SCBDR4ZG1SC019997
SCBCR2ZG9SC018127	SCBCR2ZGXSC020131	SCBDR4ZG1SC020048
SCBCR2ZG9SC018130	SCBCR2ZGXSC020145	SCBDR4ZG1SC020065
SCBCR2ZG9SC018144	SCBCR2ZGXSC020162	SCBDR4ZG1SC020096
SCBCR2ZG9SC018158	SCBCR2ZGXSC020193	SCBDR4ZG1SC020115
SCBCR2ZG9SC018161	SCBCR2ZGXSC020470	SCBDR4ZG1SC020129
SCBCR2ZG9SC019908	SCBCR2ZGXSC020484	SCBDR4ZG1SC020132
SCBCR2ZG9SC019939	SCBCR2ZGXSC020579	SCBDR4ZG1SC020180
SCBCR2ZG9SC019942	SCBCR2ZGXSC020825	SCBDR4ZG1SC020194
SCBCR2ZG9SC019987	SCBCR2ZGXSC020890	SCBDR4ZG1SC020213
SCBCR2ZG9SC019990	SCBCR2ZGXSC020954	SCBDR4ZG1SC020230
SCBCR2ZG9SC020038	SCBCR2ZGXSC021067	SCBDR4ZG1SC020289
SCBCR2ZG9SC020069	SCBCR2ZGXSC021070	SCBDR4ZG1SC020499
SCBCR2ZG9SC020072	SCBCR2ZGXSC021134	SCBDR4ZG1SC020731
SCBCR2ZG9SC020119	SCBCR2ZGXSC021215	SCBDR4ZG1SC020812
SCBCR2ZG9SC020170	SCBDR4ZG0SC019912	SCBDR4ZG1SC020874
SCBCR2ZG9SC020489	SCBDR4ZG0SC019991	SCBDR4ZG1SC020888
SCBCR2ZG9SC020525	SCBDR4ZG0SC020011	SCBDR4ZG1SC020972
SCBCR2ZG9SC021030	SCBDR4ZG0SC020073	SCBDR4ZG1SC021040
SCBCR2ZG9SC021058	SCBDR4ZG0SC020106	SCBDR4ZG1SC021121
SCBCR2ZG9SC021173	SCBDR4ZG0SC020199	SCBDR4ZG2SC019975
SCBCR2ZGXSC018119	SCBDR4ZG0SC020221	SCBDR4ZG2SC020026
SCBCR2ZGXSC018122	SCBDR4ZG0SC020297	SCBDR4ZG2SC020043
SCBCR2ZGXSC018136	SCBDR4ZG0SC020509	SCBDR4ZG2SC020124
SCBCR2ZGXSC018153	SCBDR4ZG0SC020641	SCBDR4ZG2SC020138
SCBCR2ZGXSC018167	SCBDR4ZG0SC020669	SCBDR4ZG2SC020141
SCBCR2ZGXSC019948	SCBDR4ZG0SC020865	SCBDR4ZG2SC020169
SCBCR2ZGXSC019951	SCBDR4ZG0SC021188	SCBDR4ZG2SC020172

SCBDR4ZG2SC020186	SCBDR4ZG4SC020089	SCBDR4ZG6SC019929
SCBDR4ZG2SC020253	SCBDR4ZG4SC020092	SCBDR4ZG6SC019932
SCBDR4ZG2SC020334	SCBDR4ZG4SC020156	SCBDR4ZG6SC019946
SCBDR4ZG2SC020365	SCBDR4ZG4SC020223	SCBDR4ZG6SC019977
SCBDR4ZG2SC020415	SCBDR4ZG4SC020299	SCBDR4ZG6SC019980
SCBDR4ZG2SC020530	SCBDR4ZG4SC020559	SCBDR4ZG6SC019994
SCBDR4ZG2SC020575	SCBDR4ZG4SC020755	SCBDR4ZG6SC020000
SCBDR4ZG2SC020849	SCBDR4ZG4SC020822	SCBDR4ZG6SC020045
SCBDR4ZG2SC020852	SCBDR4ZG4SC020836	SCBDR4ZG6SC020059
SCBDR4ZG2SC020883	SCBDR4ZG4SC021226	SCBDR4ZG6SC020062
SCBDR4ZG2SC021094	SCBDR4ZG4SC021243	SCBDR4ZG6SC020112
SCBDR4ZG2SC021161	SCBDR4ZG5SC019906	SCBDR4ZG6SC020126
SCBDR4ZG2SC021192	SCBDR4ZG5SC019923	SCBDR4ZG6SC020238
SCBDR4ZG3SC019953	SCBDR4ZG5SC019937	SCBDR4ZG6SC020255
SCBDR4ZG3SC020021	SCBDR4ZG5SC020005	SCBDR4ZG6SC020451
SCBDR4ZG3SC020052	SCBDR4ZG5SC020120	SCBDR4ZG6SC020580
SCBDR4ZG3SC020083	SCBDR4ZG5SC020196	SCBDR4ZG6SC020630
SCBDR4ZG3SC020102	SCBDR4ZG5SC020215	SCBDR4ZG6SC020658
SCBDR4ZG3SC020147	SCBDR4ZG5SC020294	SCBDR4ZG6SC020806
SCBDR4ZG3SC020150	SCBDR4ZG5SC020313	SCBDR4ZG6SC020871
SCBDR4ZG3SC020164	SCBDR4ZG5SC020344	SCBDR4ZG6SC020899
SCBDR4ZG3SC020228	SCBDR4ZG5SC020389	SCBDR4ZG6SC021034
SCBDR4ZG3SC020245	SCBDR4ZG5SC020635	SCBDR4ZG6SC021177
SCBDR4ZG3SC020598	SCBDR4ZG5SC020859	SCBDR4ZG6SC021194
SCBDR4ZG3SC020794	SCBDR4ZG5SC020862	SCBDR4ZG7SC019941
SCBDR4ZG3SC020844	SCBDR4ZG5SC020893	SCBDR4ZG7SC019969
SCBDR4ZG3SC021136	SCBDR4ZG5SC020909	SCBDR4ZG7SC019972
SCBDR4ZG3SC021170	SCBDR4ZG5SC021123	SCBDR4ZG7SC019986
SCBDR4ZG3SC021248	SCBDR4ZG5SC021140	SCBDR4ZG7SC020037
SCBDR4ZG4SC019962	SCBDR4ZG5SC021154	SCBDR4ZG7SC020068
SCBDR4ZG4SC020075	SCBDR4ZG5SC021218	SCBDR4ZG7SC020071

SCBDR4ZG7SC020099	SCBDR4ZG8SC021214	SCBDR4ZGXSC020078
SCBDR4ZG7SC020118	SCBDR4ZG8SC021228	SCBDR4ZGXSC020274
SCBDR4ZG7SC020183	SCBDR4ZG8SC021231	SCBDR4ZGXSC020291
SCBDR4ZG7SC020233	SCBDR4ZG9SC019956	SCBDR4ZGXSC020324
SCBDR4ZG7SC020278	SCBDR4ZG9SC020007	SCBDR4ZGXSC020338
SCBDR4ZG7SC020281	SCBDR4ZG9SC020024	SCBDR4ZGXSC020808
SCBDR4ZG7SC020328	SCBDR4ZG9SC020041	SCBDR4ZGXSC021179
SCBDR4ZG7SC020362	SCBDR4ZG9SC020086	SCBDR4ZGXSC021182
SCBDR4ZG7SC020538	SCBDR4ZG9SC020136	SCBDR4ZGXSC021201
SCBDR4ZG7SC020569	SCBDR4ZG9SC020153	SCBDR4ZGXSC021246
SCBDR4ZG7SC020751	SCBDR4ZG9SC020167	SCBCJ13S9SC021236
SCBDR4ZG7SC020796	SCBDR4ZG9SC020251	
SCBDR4ZG7SC020801	SCBDR4ZG9SC020301	
SCBDR4ZG7SC020815	SCBDR4ZG9SC020332	
SCBDR4ZG7SC020913	SCBDR4ZG9SC020413	
SCBDR4ZG7SC021172	SCBDR4ZG9SC020461	
SCBDR4ZG8SC019902	SCBDR4ZG9SC020492	
SCBDR4ZG8SC020029	SCBDR4ZG9SC020573	
SCBDR4ZG8SC020080	SCBDR4ZG9SC020587	
SCBDR4ZG8SC020094	SCBDR4ZG9SC020590	
SCBDR4ZG8SC020144	SCBDR4ZG9SC020606	
SCBDR4ZG8SC020158	SCBDR4ZG9SC020721	
SCBDR4ZG8SC020161	SCBDR4ZG9SC020833	
SCBDR4ZG8SC020175	SCBDR4ZG9SC021125	
SCBDR4ZG8SC020189	SCBDR4ZG9SC021142	
SCBDR4ZG8SC020208	SCBDR4ZG9SC021223	
SCBDR4ZG8SC020225	SCBDR4ZGXSC019898	
SCBDR4ZG8SC020242	SCBDR4ZGXSC019920	
SCBDR4ZG8SC020645	SCBDR4ZGXSC019965	
SCBDR4ZG8SC020869	SCBDR4ZGXSC020016	
SCBDR4ZG8SC020922	SCBDR4ZGXSC020033	