



Service Bulletin

Bulletin No.: PIT6345A

Date: December, 2025

PRELIMINARY INFORMATION

Subject: P059F and P05AE DTCs set in snowy or icing conditions Proactive

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2025		All	All	All	All
GMC	Terrain	2025		All	All	All	All

Involved Region or Country	North America
Condition	Vehicle may present with a CEL and DTCs P059F and P05AE.
Cause	This is likely caused by a software anomaly mixed with snow or freezing temperatures.

Correction

If no issue is found after completing the diagnostics in SI for both DTCs, do not replace the shutter assembly.

Engineering is currently investigating.

The PI will be updated or replaced with TSB once a determination has been made.

Version	1
Modified	02/21/2025 – Created on.

