

GPOP - Issue Review System

Part Number: 68457701A\$

Part Description: Mirror Mounted Ambient Temp

Issue Description: 2024-2025 DT with DTC P0070 OR P0073 If Mirror Ambient Temperature Sensor (AATS) is not reading temp correctly or setting DTC P0073, P0070 - allow the sensor to update properly by driving the vehicle at highway speeds (above 20 MPH) for several miles (15 minutes). This ensures sufficient airflow and temperature sampling for accurate readings. If the temperature still does not update, proceed with standard diagnostic procedures.

2025-2026 DT with DTC P0071 AND P0073 (vehicles built on or between 07/01/2025 - 07/29/2025 - If BOTH DTCs are present, before replacing the sensor, refer to the latest TSB in Service Library for additional repair procedure(s). - If NO DTC is present, but temperature shown in the cluster/radio is higher than expected, allow the sensor to update properly by driving the vehicle at highway speeds (above 20 MPH) for several miles (15 minutes). This ensures sufficient airflow and temperature sampling for accurate readings. If the temperature still does not update, proceed with standard diagnostic procedures.