

9100734

12/10/2025

MY 23-26 GG 22-26 DD 24-26 KM 22-26 JL
22-26 MP 22-26 RU 25-26 EJ 22-26 DJ 22-
26 JT 22-26 DP 25-26 KX 22-26 WD 19-26
GU 22-26 D2 22-26 DT 19-25 BV 22-26 WL
24-26 LB 19-26 GA 24-26 GC 22-26 WS

GPOP - Issue Review System

Part Number: 68493347

Part Description: Backup TBM Battery

Issue If the DTC B1E21-96:
Description: Backup Battery-Component Internal Failure is active and customer states Popup message will show at the radio:
"Battery of Uconnect Box requires service. SOS call and related functions may be unavailable. Please visit an authorized dealer." PLEASE do not Replace the TBM module, only replace TBM Internal Battery (inside Telematics Box Module) and order PN68493347