

Volvo Car USA LLC

Technical Journal

Technical Journal Title Ghost DTC PAS-P11C800		Ref. No. TJ 37570.1.0	
Issuer (Dept.) Technical Service		Issue Date 11/6/25	Status Date 11/13/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3871	
Function Description Parking assistance		Page Page 1 of 1	

DESCRIPTION:

If a vehicle has DTC PAS-P11C800 set, follow the advice under “Service”.

CSC Customer Symptom Codes

Code	Description
48	Parking assistance/Parking Assist Pilot (PAP) does not work

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
PAS	P11C800	Intermittent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
416							2024-9999		-	202336-999952
417							2025-9999		-	202509-999952

SERVICE:

Ignore the DTC; nothing needs to be done. This is a ghost DTC, with no actual impact on vehicle functionality.

Abbreviations:

PAS = Parking Assist System

Warranty claim info:

No warranty claim is accepted for this TJ or for the operation to clear this DTC.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support needed”, use function group 3871.