

9100747

12/15/2025

MY 25-26, 24-26 LB

GPOP - Issue Review System

Part Number: 68224760A\$, 68688994A\$

Part Description: AM/FM antenna

Issue Description: B1578 DTC active (Audio Antenna ☐ Circuit Resistance Below Threshold) in LB production vehicles. Do not diagnose stored or active DTC unless there is a customer facing issue noted. A SOL will be released to give further information.