

GPOP - Issue Review System

Part Number: 68598934

Part Description: Telematics Box Module

Issue Description: B1578 DTC active (Audio Antenna ☐ Circuit Resistance Below Threshold) in LB production vehicles. Do not diagnose stored or active DTC unless there is a customer facing issue noted. A SOL will be released to give further information.