

# Technical Service Bulletin



**97 DTC B188101 is stored in the onboard supply control unit, J519 (diagnostic address 0009)**  
97 23 91 2069405/1 February 7, 2023.

| Model(s)                                 | Year        | VIN Range | Vehicle-Specific Equipment |
|------------------------------------------|-------------|-----------|----------------------------|
| Q4 e-tron, and<br>Q4 e-tron<br>Sportback | 2022 – 2023 | All       | Not Applicable             |

## Condition

**Workshop findings:** There are no customer concerns; it is found during PDI or any other diagnostic work.  
The following DTC may be stored in the onboard supply control unit, -J519- (diagnostic address 0009):

- **DTC B188101:** Emergency path electrical error – Static/Intermittent.

## Technical Background

Software issue in the onboard supply control unit -J519- (diagnostic address 0009).

## Production Solution

Optimized software in production.

## Service

If this DTC is stored statically or intermittently with no customer concern, the DTC should be ignored. Part replacements or diagnoses should not be performed.



**Note:** This DTC **does not** affect the operation of the vehicle.

If there is a customer concern relating to exterior lighting, this DTC can be set as a secondary fault. In this case, this TSB does not apply, and the normal diagnosis should be followed.

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.  
Do not replace parts or attempt repairs.

## Additional Information



All part and service references provided in this TSB (**2069172**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©**2023 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.