

SSM 51738

2023 F-Super Duty - DTC U211B:87 Setting In Various Modules When A Diagnostic Self Test Is Performed

Some 2023 F-Super Duty vehicles may set diagnostic trouble code (DTC) U211B:87 in various modules when a diagnostic self-test is performed, which includes: powertrain control module (PCM), advanced driver assistance system (ADAS), anti-lock brake system (ABS), power steering control module (PSCM), body control module (BCM), telematics control unit (TCU), driver door module (DDM), and/or passengers door module (PDM). This may be due to the modules DTC sensitivity during vehicle key-on/start-up. Replacement or reprogramming of these module(s) may not resolve this condition. U211B:87 should be ignored if: no other DTCs are present, no warning indicators are illuminated while the engine is running and no noticeable symptoms are present. No further service action is required.