

SSM 51742

2020-2023 Mustang - Dynamic Suspension Fault Message Displayed In The Instrument Panel Cluster (IPC) With DTC B14C1:64

Some 2020-2023 Mustang (non-GT500/GT350) vehicles equipped with vehicle dynamic suspension may exhibit a Dynamic Suspension Fault message displayed in the IPC with diagnostic trouble code (DTC) B14C1:64 with no vehicle symptoms. This may be due to software within the vehicle dynamics module (VDM). To correct the condition, reprogram the VDM using the latest software level of the appropriate Ford diagnostic scan tool.