



**IMPORTANT SERVICE
INFORMATION FOR:**

- ✓ SERVICE MANAGER
- ✓ SERVICE ADVISOR
- ✓ TECHNICIAN
- ✓ PARTS DEPARTMENT
- ✓ WARRANTY PERSONNEL

BULLETIN NUMBER:
SB23-L-001

ISSUE DATE:
JUNE 2023

GROUP:
FUEL & EXHAUST

DTC P2201 CALIBRATION UPDATE - REPROGRAM DEF CONTROL UNIT (DCU)

AFFECTED VEHICLES

- 2021MY Isuzu F-Series Vehicles

INFORMATION

The vehicle's Check Engine Malfunction Indicator Lamp (MIL) may illuminate with DTC P2201 set in the DEF Control Unit (DCU). If the preceding DTC is present, first follow the diagnostic for the DTC in question. If no mechanical fault can be found during normal diagnosis, follow the service procedure in this bulletin to correct the concern.

SERVICE PROCEDURE

If the calibration part number does **NOT** match the calibration number listed in the table below, reprogram the DCU with the latest software and calibration using the Isuzu Diagnostic Service System (IDSS) version 15.0.2 or later:

MY	Vehicle	Engine	Calibration #
2021	F-Series	5.2L	55202829

NOTE: If the calibration number IS listed above, follow the Intermittent Conditions diagnostics in the appropriate Workshop Manual.

WARRANTY INFORMATION

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
L8004	CALI UPDATE REPRGM DCU P2201	0.4