

A4 Golf Jetta Beetle B5 Passat

Updated Software						Technical		
Model Year	Model	Engine	Concern	Module Part #	New Part #	Level	Bulletin #	SVM or Disc
2002	Cabrio	2.0L ABA	P0102, P1128, P1296	037906018G	037906018G	V07	01-08-16	W42CABRIOSWU9820REV SVM 34E6
				037906018H	037906018H	V06		
1999-2001	Beetle	1.8T APH	P1176	06A906032B	06A906032S	5829	01-06-03	Replace ECM
				06A906032E	06A906032R	5828		
				06A906032A	06A906032Q	5827		
				06A906032C	06A906032P	5826		
1999-2001	Golf Jetta Beetle	2.0L AEG	WA Front Oxygen Sensor faults	06A906018ES	06A906018JJ	V01	WA00	3060
				06A906018ET	06A906018JK			
				06A906018FA	06A906018JL			
				06A906018FB	06A906018JM			
				06A906018EN	06A906018JN			
				06A906018EP	06A906018JP			
				06A906018EQ	06A906018JQ			
				06A906018ER	06A906018JR			
				06A906018J	06A906018JA			
				06A906018BJ	06A906018JB			
				06A906018BG	06A906018JC			
				06A906018BH	06A906018JD			
				06A906018CR	06A906018JE			
				06A906018CQ	06A906018JF			
				06A906018P	06A906018JG			
				06A906018AE	06A906018JH			
2001-2005	A4 Jetta GTI	1.8T AWW 1.8T AWP 1.8T AWD	P0420, P0442 or cold start misfires	06A906032DL	06A906032DL	0007	01-09-10	3061
				06A906032GH	06A906032GH	0007		
				06A906032HF	06A906032SL	0040		
				06A906032LQ	06A906032SL			
				06A906032NL	06A906032SL			
				06A906032HS	06A906032SK	0040		
				06A906032LP	06A906032SK			
				06A906032NK	06A906032SK			
				06A906032ML	06A906032SM	0040		
				06A906032PL	06A906032SM			
				06A906032RN	06A906032SM			

A4 Golf Jetta Beetle B5 Passat Continued

					Updated Software		Technical	
Model Year	Model	Engine	Concern	Module Part #	New Part #	Level	Bulletin #	SVM or Disc
2001-2004	Beetle	1.8T AWP 1.8T AWU 1.8T AWV	P0420 or P0442 Cold start misfires	06A997012	06A997012	9777	01-09-07	3005
				06A906032QA				
				06A906032LS				
				1C0906032				
				06A997012A	06A997012A	9776		
				06A906032GA				
				06A906032KR				
				06A906032PR				
				06A997012B	06A997012B	9775		
				06A906032GB				
				06A906032KQ				
				06A906032PT				
				06A997012C	06A997012C	9778		
				06A906032KT				
				06A906032PS				
				06A906032EM				
06A906032DN	06A906032EM	9774						
06A906032FD								
06A906032DP	06A906032FD	9773						

2005	Beetle	1.8T BKF 1.8T BNU	P0420. Also addresses P0300 - P0304 on cold start	06A906032QT	06A906032QT	9784	01-08-10	W42200518TSWU SVM 3486
				06A906032QS	06A906032QS	9785		
				06A906032RA	06A906032RA	9786		

1999-2002	Golf Jetta	2.8L AFP	N7 ECM Software for Catalytic Converter Monitoring System	021906018A	021906018A	6781	26E1	306B
				021906018B	021906018B	6782		
				021906018K	021906018K	6758		
				021906018M	021906018M	6760		
				021906018Q	021906018Q	6759		
				021906018R	021906018R	6762		
				021906018S	021906018S	6761		
				021906018T	021906018T	6764		
				021906018AA	021906018AA	6763		

2002-2004	A4 Jetta	2.8L BDF	P0420 and/or P0300 - P0306	022906032BL	022906032BL	1479	01-08-14	3000
				022906032BM	022906032BM	1480		
				022906032CR	022906032CR	1481		
				022906032CS	022906032CS	1482		
				022906032DM	022906032DM	1483		

A4 Golf Jetta Beetle B5 Passat Continued

Updated Software						Technical		
Model Year	Model	Engine	Concern	Module Part #	New Part #	Level	Bulletin #	SVM or Disc
2002-2004	A4 Golf	2.8L BDF	P0420 and/or P0300 - P0306	022906032BM	022906032BM	1480	01-08-22	3001
				022906032CS	022906032CS	1482		
				022906032DM	022906032DM	1483		
2000-2005	B5 Passat	1.8T ATW 1.8T AUG 1.8T AWM	P0300-P0304 at cold start or P0102, P1297, P0420 or P0441	4B0906018BH	4B0906018BH	0009	01-09-09 R5	3061
				4B0906018BG	4B0906018BG	0009		
				4B0906018BQ	4B0906018BQ	0004		
				4B0906018CL	4B0906018CL	0003		
				4B0906018CM	4B0906018CM	0010		
				4B0906018DA	4B0906018DA	0060		
				4B0906018DN	4B0906018DN			
				4B0906018DP	4B0906018DP			
				4B0906018DQ	4B0906018DQ	0009		
				4B0906018Q	4B0906018Q			
				4B0906018P	4B0906018P			
2000-2001	B5 Passat	2.8L ATQ	P0420	3B0907551AN	3B0907551AN	0050	01-07-07	8D0 906 961 A SVM 34DB
				3B0907551G	3B0907551G	0050		8D0 906 961 B SVM 34DC
				3B0907551BA	3B0907551BA	0050		8D0 906 961 D SVM 34DD
2004	B5 Passat	2.8L ATQ	Harsh 3-2 downshift	3B0 927 156 BA	3B0 927 156 BA	2225	01-07-18	W42PASSATSHIFT SVM 3534
				3B0 927 156 AT	3B0 927 156 AT			
2002 - 2003	B5 Passat	4.0 BDP	P0456 (Flashes ECM and TCM)	07D906018E	07D906018E	5088	01-07-38	W42W8UPDATECD SVM 34E0
				3B0927156T	3B0927156T	2222		
2004-2005	Beetle	1.9L BEW	Hard start or no start at or below 0°C (32°F) and/or runs rough after 28F6 Campaign	038906016P	038997016S	0283	28-10-05	3456
	Golf Jetta			038906016J				
				038906016M				
				038906016Q				
				038906016H				
		038906016L						
	Passat	2.0L BHW		038997016L	038997016R	0282		
				038997016R				
				038997016N				

A5 Golf Jetta B6 Passat

Updated Software						Technical		
Model Year	Model	Engine	Concern	Module Part #	New Part #	Level	Bulletin #	SVM or Disc
2006-2008	A5 GTI A5 Jetta Eos B6 Passat	2.0L BPY	P0601 or P0642, P2004, P2008, P3137, P3138	1K0907115B	1K0907115B	0040	24M2/O3 RVU 01-09-18	301D
				1K0907115H	1K0907115H	0040		1FDD
				1Q0907115B	1Q0907115E	0020		301D will update ECM and TCM
				1Q0907115D		0020		
				1Q0907115E		0020		
				3C0907115F		3C0907115F		
				3C0907115G	3C0907115G	0030		
				3C0907115P	3C0907115P	0020		
				3C0907115S	3C0907115S	0020		
		09G	Various shifting concerns	09G927750FP	09G927750HJ	1068		300B will update TCM only
				09G927750CJ	09G927750HJ	1068		
2007-2008	Jetta Passat	2.0L BPY	ECM/TCM Software Update and Valve Body Replacement for Harsh Up - Down Shift from Transmission when Cold	3C0907115P	3C0907115S	0020	01 11 30	320A
				3C0907115S		0020		
				09G927750FP	09G927750C	1616		
				09G927750HJ		1617		
				09G927750FL	09G927750D	1649		
				09G927750D		1649		
				09G927750HE	09G927750E	1615		
2006-2007	B6 Passat B6 Passat Wagon	3.6L	Mil and/or Oil pressure light comes on	03H906032B	03H997033M	2370	24L8/O2 Update 01-08-19	3016
		09G Trans		03H906032C	03H997033N	2371		
				09G927750AJ	09G927750HK	1271		
				09G927750FR				
				09G927750HK				

A5 Golf Jetta B6 Passat Continued

Updated Software						Technical		
Model Year	Model	Engine	Concern	Module Part #	New Part #	Level	Bulletin #	SVM or Disc
2007	A5 Jetta A5 Rabbit	2.5L BGP 2.5L BGQ	P0011, P000A, or Exhaust noise on cold start	07K906032Q	07K906032Q	9650	01-07-57	W420607A5SWU SVM 34FC
				07K906032R	07K906032R	9651		
				07K906032S	07K906032S	9652		
				07K906032T	07K906032T	9653		
2007	Beetle	2.5L BPR 2.5L BPS		07K906032AA	07K906032AA	9654		
				07K906032AB	07K906032AB	9655		
				07K906032AC	07K906032AC	9656		
				07K906032AD	07K906032AD	9657		
2006	A5 Jetta	2.5L BGP 2.5L BGQ		07K906032L	07K906032AN	9683		
				07K906032M	07K906032AP	9684		
				07K906032N	07K906032AQ	9685		
				07K906032P	07K906032AR	9686		
2006	Beetle	2.5L BPR 2.5L BPS		07K906032	07K906032AS	9687		
				07K906032A	07K906032AT	9688		
				07K906032B	07K906032BA	9689		
				07K906032C	07K906032BB	9690		
2006	All	09G	Trans update	09G927750AS	09G927750ASGJ	0833		
				09G927750EL				

A5 Golf Jetta B6 Passat Continued

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM or Disc</u>
2005	A5 Jetta	2.5L BGP BGQ	P3081 and Noise after Starting Cold	06A906032QC	06A906032QC	9422	01 11 04	348F
				06A906032QE	06A906032QE	9424		
				09G927750AS	09G927750AS	1205		
2009-2010	A5 Jetta A5 Rabbit	2.5L CBUA	DTC P0145 stored in ECM Fault Memory	07K906055AG	07K906055AG	9750	01 12 21	3536
				07K906055AF	07K906055AF	9751		
				07K906055M	07K906055M	9752		
				07K906055N	07K906055N	9753		
2009-2010	A5 Jetta A5 Rabbit	2.5L CBTA CBUA	Engine Difficult to Start in Temperatures Below 32 degrees F (0 degrees C)	07K906055AG	07K906055AG	9970	01 12 22	3565
				07K906055AF	07K906055AF	9970		
				07K906055M	07K906055M	9970		
				07K906055N	07K906055N	9970		
				07K906055AJ	07K906055AJ	9970		
				07K906055AH	07K906055AH	9970		
				07K906055Q	07K906055Q	9970		
				07K906055P	07K906055P	9970		
2009	A5 Jetta A5 Rabbit	2.5L CBUA 2.5L CBTA	P150A	07K906055M	07K906055M	3859	01 13 29	3565
				07K906055N	07K906055N	3860		
				07K906055P	07K906055P	3861		
				07K906055Q	07K906055Q	3862		
2009	A5 Jetta A5 Rabbit	2.5L CBUA 2.5L CBTA	A/C cooling efficiency	07K906055M	07K906055M	3859	01-08-29	30F5
				07K906055N	07K906055N	3860		
				07K906055P	07K906055P	3861		
				07K906055Q	07K906055Q	3862		

Golf Jetta 2.0L Common Rail TDI

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM or Disc</u>
2009-2011	Jetta	2.0L CBEA 2.0L CJAA	P0136, P0139, P2271, P00D5, P013B and/or P320C; P0101 P0102	03L906022KS	03L997016N	8680	23 11 01 23H1	3339
				03L906022PC		8680		
				03L906022KT	03L997016P	8681		
				03L906022PD		8681		
				03L906022TS	03L906019CL	7966		
				03L906022TT	03L906019CM	7967		
				03L906019DA	03L906019DA	8217		
				03L906019DB	03L906019DB	7970		
2011	Jetta Golf	2.0L CJAA	DTC P2458 Stored in ECM Fault Memory	03L906022KB	03L906022KB	9044	01 13 18	3339
				03L906022PB	03L906022PB	9045		
				03L906019DA	03L906019DA	9144		
				03L906019DB	03L906019DB	9047		
2012	Jetta Golf	2.0L CJAA	P240F	03L906019EG	03L906019HH	3524	01 13 07	3820
				03L906019EH	03L906019EH	3523		
				03L906019EF	03L906019HG	3522		
				03L906019EE	03L906019EE	3521		
2012	Jetta Golf	2.0L CJAA	Slight Hesitation Concerns	03L906019EF	03L906019HG	3522	01 12 36	36C6
				03L906019EG	03L906019HH	3524		
				02E300057A	02E300058M	3524		
				02E300057P	02E300058M	3524		
2013	Jetta Golf Beetle	2.0L CJAA	P00AF	03L906019HB	03L906019HB	4604	01 13 06	384A
				03L906019HC	03L906019HC	4603		
				03L906019AP	03L906019AP	4601		
				03L906019AN	03L906019AN	4602		
				03L906019HE	03L906019HE	4606		
				03L906019HD	03L906019HD	4605		

A6 Golf EOS Passat CC Tiguan

				Updated Software		Technical		
Model Year	Model	Engine	Concern	Module Part #	New Part #	Level	Bulletin #	SVM or Disc
2007-2008	Eos	3.2L BUB CBRA	DTCs P0420 and P0430 Stored in ECM Fault Memory	022906032CF	022906032CF	9971	01 11 10	3550
				022906032LF	022906032LF	9189		
				022906032KR	022906032KR	1319		
2008-2012	Tiguan, CC, Passat	2.0T CCTA CBFA	P150A Stored in ECM Fault Memory	06J906026F	06J906026F	4296	01 12 11	306A
				06J906026G	06J906026G	4297		
				06J906026H	06J906026H	4298		
				06J906026AF	06J906026AF	4060		
				06J906026AG	06J906026AG	4061		
				06J906026BR	06J906026BR	4063		
				06J906026BJ	06J906026BJ	4062		
2012	CC	2.0T CBFA CCTA	Stumbling or Rough Running Conditions at Low Speeds	Vehicles with Manual Transmission			01 12 27	3733
				06J906027F	06J906027F	9924		
				06J906027CL	06J906027CL	1122		
				06J906027DD	06J906027FE	3952		
				06J906027G	06J906027G	9970		
				06J906027CK	06J906027CK	4500		
				06J906027DC	06J906027FD	3951		
				Vehicles with Automatic Transmission				
				06J906027F	06J906027FE	3952		
				06J906027CL				
				06J906027DD				
				06J906027FE				
				06J906027G	06J906027FD	3951		
				06J906027CK				
				06J906027DC				
				06J906027FD				
				02E300053M	02E300058N	3509		
				02E300058E				
				02E300054M				
				02E300057B				
				02E300057Q				

A6 Golf EOS Passat CC Tiguan Continued

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM or Disc</u>
2011-2012	Eos, CC	2.0T CBFA	DTC P050A and High Idle Faults Stored in ECM Fault Memory	06J906027AA	06J906027AA	9654	01 11 21	3642
				06J906027CH	06J906027CH	1440		
				06J906027AR				
				06J906027AC	06J906027AC	9655		
				06J906027G	06J906027CK	0894		
2010-2013	Passat CC	2.0T CCTA CBFA	Current ECM/TCM programming may cause stumble depending on driving conditions	06J906027AB	06J906027AB	7378	24X8	3733
				06J906027AC	06J906027AC	9970		
				06J906027F	06J906027FE	3952		
				06J906027G	06J906027FD	3951		
				02E 300 058N	02E 300 058N	3509		
2010	B6 Passat CC Eos Tiguan	2.0L CCTA 2.0L CBFA	Coolant Pump Activation	06J906021	06J906021	6992	24R9/YR Update 24-10-04	3356
				06J906021C	06J906021C	6993		
				06J906021DA	06J906021DA	6987		
				06J906021DP	06J906021DP	6988		
				06J906021DN	06J906021DN	6989		
				06J906021DR	06J906021DR	6990		
				06J906021B	06J906021B	6991		
				06J906021DQ	06J906021DQ	6995		

NMS Passat Common Rail TDI

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM or Disc</u>
2012	Passat	2.0L CKRA	P2201	03L906012BP	03L906012BN	5558	01 13 04	3810
2012	Passat	2.0L CKRA	P050E P2080 P244C P2478	03I906012BP	03I906012BP	4270	01 13 03	35F3
				03L906012	03L906012	4269		
2013	Passat	2.0L CKRA	P00AF P1388 P0606 P2201	03L906012BN	03L906012BN	4804	01 12 35	35F3
				03L906012BM	03L906012BM	4824		

A6 Jetta B7 Passat New Edition Beetle

Model Year	Model	Engine	Concern	Module Part #	New Module Part #	Updated Software Level	Technical Bulletin #	SVM Unit
2011-2013	Jetta Golf Passat Beetle	2.5L CBTA CBUA	P0106	07K906055DA	07K906055DA	4731	01 13 25	3723
				07K906055BE				
				07K906055CT	07K906055CT	4732		
				07K906055BD				
				07K906055CL	07K906055CL	4747		
				07K906055CK	07K906055CK	4748		
				07K906055DH	07K906055DH	4739		
				07K906055BC				
				07K906055DG	07K906055DG	4740		
				07K906055BB				
				07K906055CQ	07K906055CQ	4729		
				07K906055DB	07K906055DB	4730		
				07K906055E	07K906055E	4745		
				07K906055D	07K906055D	4746		
				07K906055DF	07K906055DF	4737		
				07K906055C				
				07K906055DE	07K906055DE	4738		
				07K906055B				
				07K906055CP	07K 906 055CP	4725		
				07K906055G				
				07K906055CN	07K 906 055CN	4726		
				07K906055F				
				07K906055CJ	07K906055CJ	4741		
				07K906055CH	07K906055CH	4742		
				07K906055DK	07K906055DK	4733		
				07K906055DJ	07K906055DJ	4734		
				07K906055				
				07K906055A	07K906055DK	4733		
				07K906055CR	07K906055CR	4727		
				07K906055CS	07K906055CS	4728		
				07K906055DD	07K906055DD	4735		
				07K906055AN				
				07K906055AM	07K906055DC	4736		
				07K906055DC				
				07K906055AL	07K906055AL	4743		
				07K906055AK	07K906055AK	4744		

A6 Jetta B7 Passat New Edition Beetle Continued

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Module Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM Unit</u>
2011-2013	Jetta Golf Passat Beetle	2.5L CBTA CBUA	Harsh Bump Stop	07K906055DA	07K906055DA	4731	01 13 26	3723
				07K906055BE				
				07K906055CT	07K906055CT	4732		
				07K906055BD				
				07K906055CL	07K906055CL	4747		
				07K906055CK	07K906055CK	4748		
				07K906055DH	07K906055DH	4739		
				07K906055BC				
				07K906055DG	07K906055DG	4740		
				07K906055BB				
				07K906055CQ	07K906055CQ	4729		
				07K906055DB	07K906055DB	4730		
				07K906055E	07K906055E	4745		
				07K906055D	07K906055D	4746		
				07K906055DF	07K906055DF	4737		
				07K906055C				
				07K906055DE	07K906055DE	4738		
				07K906055B				
				07K906055CP	07K 906 055CP	4725		
				07K906055G				
				07K906055CN	07K 906 055CN	4726		
				07K906055F				
				07K906055CJ	07K906055CJ	4741		
				07K906055CH	07K906055CH	4742		
				07K906055DK	07K906055DK	4733		
				07K906055DJ	07K906055DJ	4734		
				07K906055				
				07K906055A	07K906055DK	4733		
				07K906055CR	07K906055CR	4727		
				07K906055CS	07K906055CS	4728		
				07K906055DD	07K906055DD	4735		
				07K906055AN				
				07K906055AM	07K906055DC	4736		
				07K906055DC				
				07K906055AL	07K906055AL	4743		
				07K906055AK	07K906055AK	4744		

A6 Jetta B7 Passat New Edition Beetle Continued

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Module Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM Unit</u>
2012	Jetta Golf Beetle	2.5L CBTA CBUA	Slight Hesitation Concerns	07K906055A	07K906055A	9740	01 12 15	3723
				07K906055CJ	07K906055CJ	3691		
				07K906055BC	07K906055BC	9738		
				07K906055CL	07K906055CL	3692		
				07K906055C	07K906055C	3116		
				07K906055E	07K906055E	3689		
2011-2012	Jetta Golf	2.5L CBUA CBTA	Harsh Engagement from Part to Drive or Reverse	09G927750LH	09G927750LH	1916	01 11 15	3548
				09G927750LM	09G927750LM	1919		
				09G927750LF	09G927750LF	1914		
2011	GTI	2.0L CBFA CCTA	Eliminate Rough or Low Idle after Startup	1K0907115AQ	1K0907115AQ	0040	01 11 14	3643
				1K0907115AP	1K0907115AP	0040		
2011	Jetta	2.0L CBPA	DTC P050A Stored in ECM Fault Memory	06G906055B	06G906055B	1109	01 11 06	3522
				06G906055C	06G906055C	1108		
2011	Jetta	2.0L CBPA	DTC P050A Stored in ECM Fault Memory	06G906055B	06G906055B	1109	01 13 28	3522
				06G906055C	06G906055C	1108		
2011	Jetta	2.0L CBPA	DTC 03366 Stored in Brake Electronics Fault Memory	06G906055T	06G906055T	1205	01 13 27	3801
				06G906055R				
				06G906055B				
				06G906055AA	06G906055AA	1205		
				06G906055S				
				06G906055C				
2013	Jetta	1.4L CNLA	P0087 P119A P164B P30A1	04E906023	04E906023	5631	01 13 15	384C
				5C0907080C	5C0907080C	0535		

Control Module Update Quick Reference Guide

Touareg								
Model Year	Model	Engine	Concern	Module Part #	New Module Part #	Updated Software Level	Technical Bulletin #	SVM Unit
2004	Touareg	3.2L BAA	P0420 or P0430 Cold start misfires P0300-P0306	022906032BF	022906032BF	9779	01-08-11	2097
2004	Touareg	4.2L AXQ	V8 poor throttle response	4D0 907 560 DA	4D0 907 560 DA	0050	01-05-04	W42TOURSWU0050 SVM 3490
2004-2006	Touareg	ALL	Drivetrain Binding/Tires Scrubbing During Low Speed Maneuvering ESP Light ON or Flashing	0AD927755BE	0AD927755BE	0122	01 11 29	349C
2005-2006	Touareg	3.2L BMX	P0420 or P0430 Cold start misfires P0300-P0306	022906032FT	022906032GT	9911	01-08-13	301E
				022906032GT	022906032GT			
2006	Touareg	4.2L AXQ	A/C not blowing cold	4D0907560DF	4D0907560DF	0030	01-07-53	20B0
2006-2007	Touareg	3.6L	Mil and/or Oil pressure light comes on	03H906032AG	03H997033R	2374	24L8/O2 Update 01-08-19	3017
		09D Trans		03H906032D	03H997033P	2372		
				09D927750FF	09D927750FF	1274		
				09D927750CP	09D927750CP	1273		
2006-2007	Touareg	5.0L (TDI) BWF	Low load vibrations	070906016AE	070906016CQ	9805	01-09-08	3004
				070906016BG				
				070906016BJ				
				070906016CQ				
2007	Touareg	4.2L BAR	P0601	7L0910560F	7L0910560F	0020	01-10-14	3107

Touareg continued

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Module Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM Unit</u>
2011-2012	Touareg	3.6L CGRA	Eliminate Cold Start - Rough Idle Concern	03H906023B	03H906023B	8688	01 13 09	35F4
				03H906023AG	03H906023AG	2580		
2011-2012	Touareg	3.0L CATA	P0263 P0266 P0269 P0272 P0275 P0278	7P0907401E	7P0907401J	0004	01 13 11	363C
2011-2012	Touareg	3.0L CATA	AdBlue light On with DTC's P20E8, P20B7, and or P202A stored in ECM Fault Memory	7P0907401E	7P0907401J	0002	26 12 01	363C
2013	Touareg	3.0L CNRB	P0299 P0403 P20EE P2100 P0045 P2008 P24AF P026A P050E	7P0907401K	7P0907401K	0004	01 13 12	38A7

Control Module Update Quick Reference Guide

Routan								
<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Module Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM Unit</u>
2010	Routan	4.0L CGVA	P050D (UNSOLD VEHICLES)	VIN Range DX AR000001 To DX_AR209424			24I3/YK RVU 24-10-01	Star MOBILE
2010	Routan	4.0L CGVA	P050D	VIN Range DX AR000001 To DX_AR209424			01-10-03	Star MOBILE
2010	Routan	3.8L CGUA	P013A (UNSOLD VEHICLES)	All			24S3/YQ RVU 24-10-03	Star MOBILE
2009-2010	Routan	3.8L CGUA	P013A	VIN Range 41_9R000001 To D1_AR195846			01-10-02	Star MOBILE
2009	Routan	3.8L CGUA	Reprogram Oil change indicator system	All			17D4/Y7 RVU 24-09-01	Star MOBILE
2009	Routan	4.0L CGVA	Reprogram PCM for Thrust bearing	All			37E9/YB RVU 01-09-17	Star MOBILE
2009	Routan	All	P2181	All			01-10-12	Star MOBILE

Transmission Control Module Updates

Model Year	Model	Engine	Concern	Module Part #	New Module Part #	Updated Software Level	Technical Bulletin #	SVM Unit
2012	Jetta, Passat, Beetle, CC, Tiguan, Golf	2.5L CBUA CBTA 2.0T CCTA 3.6L CNNA	Fault Code 00266 Stored in TCM Read will only flash certain Software Levels	09G927750HG	09G927750HG	2038->2172	01 12 12	36AD
				09G927750JE	09G927750JE	2034->2169		
				09G927750MH	09G927750MH	2061->2195		
				09G927750LM	09G927750LM	2044->2178		
				09G927750LR	09G927750LR	2062->2196		
				09G927750LE	09G927750LE	2040->2174		
				09G927750LF	09G927750LF	2041->2175		
				09G927750LG	09G927750LG	2042->2176		
				09G927750LH	09G927750LH	2043->2177		
2012	Tiguan	2.0L CCTA	Slight Hesitation and or Driving Noise at Low Speeds in High Gear	09G927750LR	09G927750NK	2253	01 12 13	3703
						2248		
2009	Tiguan	2.0L CCTA	Harsh 3-2 down shift when cold	09G927750GG	09G927750GG	1702	01-09-19	32E1
				09G927750KM	09G927750KM	1703		
				09G927750KN	09G927750KN	1704		
2008	A5 Jetta A5 GTI	2.0L BPY	Harsh 1-2 or 2-3 up shift	1K0907115S	1K0907115S	0040	01-09-14	317D
				02E300044J	02E300044J	1416		
2007	A5 Jetta/GTI	2.0L BPY	Launch Control Program	02E325025AD	02E325025AD	1158	37-07-09	W42DQ250RD2 SVM 3601

Transmission Control Module Updates

Model Year	Model	Engine	Concern	Module Part #	New Module Part #	Updated Software Level	Technical Bulletin #	SVM Unit
2007-2008	B6 Passat	2.0L BPY	ECM, TCM Software Update and Valve Body Replacement for Harsh Up - Down Shift from Transmission when Cold; see TB	3C0907115P	3C0907115S	0020	01-11-30	320A
				3C0907115S		0020		
				09G927750FP	09G927750C	1616		
				09G927750HJ		1617		
	A5 Jetta	2.5L		09G927750FL	09G927750D	1649		
				09G997750D		1649		
				09G927750HE	09G927750	1615		
2006-2007	B6 Passat	2.0L BPY	Harsh Downshift after Extended Highway Driving	09G927750FP	09G927750FP	1199	01 11 31	300B
				09G927750CJ	09G927750CJ	1135		
2006	B6 Passat	2.0L BPY	Harsh 5-4 downshift	09G927750CJ	09G927750CJ	1135	01-09-15	300B
1999-2002	A4 Golf/Jetta	2.8L AFP	Automatic transmission, slips when shifting from 2nd to 3rd gear	01M927733MP	01M927733MP	5060	37-07-05	Replace TCM
				01M927733DJ				
				01M927733JS				
				01M927733KR				
				01M927733MB				
				01M927733MH				

Radio / Navigation								
<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Module Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM Unit</u>
2010	CC Eos Golf/GTI Jetta□ Passat Tiguan	All	Radio, RCD510 (Premium 8)	See TB		0043	91-10-19	SD card RCD510SW0043
2009	A5 Jetta GTI Eos Tiguan Passat & CC Touareg	All	RNS 510 unable to load map data (U.S. only)	3C0 035 684 + index 7L6 035 684 + index		Map Data Only	91-10-22	RNS510SD2019935
2009	A5 Jetta A5 GTI Eos Tiguan B6 Passat B6 Passat Cc Touareg	All	RNS 510 with various concerns	3C0 035 684 + index		380/382	91-10-21	RNS510FLSH0380
				7L6 035 684 + index				

Radio / Navigation Continued

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Module Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM Unit</u>
2005-2008	A5 Jetta B6 Passat Eos	All	Radio, navigation system, operating errors	1K0 035 197 + index		50	91-09-04	N/AVFLTAYSW50
2005-2008	A5 Jetta, B6 Passat GTI, Rabbit EOS	All	Premium 7 (6 disc changer, Panasonic Only) Corrects issues related to "amp clipping", reception issues, satellite radio inoperative, "bass flare", and radio does not power down when door open with key off	1K0 035 180 + index		35	91-09-06	PANFLSW0035 SVM 34A6
2008	Touareg 2	All	DVD navigation update, complaints of loss of presets in satellite radio mode	7L6 035 177 + index		30	91-08-02	N/AVFLASW30
2005-2007	Touareg	All	DVD navigation update	7L6 035 191 + (D/Q/S)		49	91-09-19	N/AVFLTOR49
2004-2005	Touareg	All	Complaints of battery drain and/or no start condition	7L6 035 191 + (A/B/D/E)		0635	91-09-01	W42TOURN/AV

Control Module Update Quick Reference Guide

Miscellaneous Control Units

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Complaint</u>	<u>Module Part #</u>		<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>CD or SVM</u>
2011	GTI Jetta Tiguan	All	Electronic Steering Column Lock w/ Kessy	5K0905861	5K0905861	120	28 11 01 96B7	3478
2010	Routan	90	Instrument cluster ambient temperature reading slow to react or inaccurate	N/A		N/A	90-10-06	Scan Tool ECU Flash
2010	Routan	97	TIPM Update	N/A		N/A	90F3/YJ RVU 97-10-01	Star MOBILE
2010	A6 Golf A6 GTI	97	Body Control Module Update	N/A		0576	97T2/YW RVU 97-10-08	33BC
2009-2010	Passat, CC	90	Update programming, gateway control module, incorrect message in multifunction display (MFD)	3C0907530J	3C0907530J	0172	90-10-07	332B
				3C0907530K	3C0907530P			
				3C0907530P	3C0907530P			
				3C0907530L	3C0907530Q			
				3C0907530Q	3C0907530Q			
				3C0907530M	3C0907530N			
				3C0907530N	3C0907530N			
2009	B6 Passat, Passat Wagon, CC	90	Software update for instrument cluster compass display	N/A	See TB	N/A	90-10-02	3176
2009	B6 Passat, CC	90	DTC 01317 Stored in instrument cluster control module -J285- or other control modules	3C0907530F SW 0142	3C0907530J	0048	90-09-02	31D2

Miscellaneous Control Units Continued

Model Year	Model	Engine	Complaint	Module Part #		Updated Software Level	Technical Bulletin #	CD or SVM
2008-2010	A5 Jetta A5 Rabbit GTI, R32 Eos Tiguan	90	Gateway control unit Update programming, Parking brake cannot be switched off, incorrect symbols in dash display	1K0907530L	1K0907530AD	0112	90-11-03	328C
				1K0907530Q				
				1K0907530S				
				1K0907530AA				
				1K0907530AD				
				1K0907530N	1K0907530AE			
				1K0907530R				
				1K0907530T				
				1K0907530AB				
				1K0907530AE				

2005-2009	A5 Jetta A5 Rabbit GTI, R32 Eos Tiguan B6 Passat & CC	48	Steering system adaption Note: Applies to all steering rack replacements	N/A	See TB	N/A	48-09-01	W42RACKMAP50 SVM 337D
-----------	--	----	---	-----	--------	-----	----------	--------------------------

2005-2009	A5 Jetta A5 Rabbit GTI, R32 Eos Tiguan	91	Cruise control inoperative, DTC 18104 and/or DTC 18106 present Note: Unflashed vehicles will have a zero for the last digit of the software level	N/A		XXX1	27-09-03	Scan tool test plan "Adaptation cruise control system debounce counter"
-----------	--	----	--	-----	--	------	----------	---

2005-2009	A5 Jetta A5 Rabbit GTI, R32 Eos Tiguan	91	Steering wheel menu change buttons inoperative	N/A	See TB	N/A	90-09-01	Scan tool test plan "Adaptation menu key multifunction steering wheel"
-----------	--	----	--	-----	--------	-----	----------	--

Miscellaneous Control Units Continued

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Complaint</u>	<u>Module Part #</u>		<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>CD or SVM</u>
2004-2008	Beetle & Beetle Convertible A5 Jetta GTI, R32 B6 Passat	69	Airbag Pods system faults DTC 02511 014	N/A	See TB	N/A	01-08-07	W42DTC02511014 - 2
2006-2007	B6 Passat	45	EPB update to prevent false DTC's: 00446 002, 00532 002, 02428 002, 0229 002, 02433 011, 02433 012	3C0907801B	3C0907801BZ	0001	01-07-47	2084
				3C0907801E				
2007	Eos	57	OS update TPMS and comfort module	N/A	See TB	0218	01-06-20	W42INSTKUPDATECD SVM 34A6
2008 - 2009	Touareg	90	Menu options missing from MFI	Multiple	See TB	9533	90-08-07	Multiple
2007-2009	Eos	91	Compass reads incorrectly (Non navigation vehicle)	1Q0919965	See TB	0002	91-09-25	COMPASFLASHSW002 SVM 34F8
2004	Touareg	90	Touareg clock loses time Read TB; Two Part Flash	7L6 920 980 M, N, P	See TB	2922	90-08-02	W42TOURCLUSTER SVM 34DF
				7L6 920 970 L, M		1822		
				7L6 920 870 M, N, P		2922		
				7L6 920 880 L, M		1822		
2004	Phaeton	90	Analog clock runs slow (Infotainment)	N/A		0223	90-07-01	Call Helpline
2004	Phaeton	90	Instrument cluster display distortion	N/A		0321, 0421, 0521	90-06-02	Call Helpline
2000	A4 Golf A4 Jetta	90	VS campaign instrument cluster update	N/A		N/A	VS	VW18192804

Vehicle Updates

Updated Software						Technical		
Model Year	Model	Engine	Concern	Module Part #	New Part #	Level	Bulletin #	SVM Unit
2009-2011	A5 Jetta A5 JettaWagon	2.0L CBEA 2.0L CJAA	P0136, P0139, P2271, P00D5, P013B and/or P320C; P0101 P0102	03L906022KS	03L997016N	8680	23 11 01 23H1	3339
				03L906022PC	03L997016N	8680		
				03L906022KT	03L997016P	8681		
				03L906022PD	03L997016P	8681		
				03L906022TS	03L906019CL	7966		
				03L906022TT	03L906019CM	7967		
				03L906019DA	03L906019DA	8217		
				03L 906 019DB	03L 906 019DB	7970		
2011-2012	Touareg	3.0L CATA	P208C P208E P20EE P150A	7P0907401E	7P0907401J	0003	26 12 01 23K9	363C
				7P0907401J				
2013	Passat	2.0L CKRA	ECM/EDC Software	03L906012BN	03L906012BN	4804	01 12 35 23L3	35F3
				03L906012BM	03L906012BM	4824		
2010	Tiguan Passat CC EOS	CCTA CBFA	Coolant Pump Activation	06J906021	06J906021	6992	24 10 04 24R9	3356
				06J906021C	06J906021C	6993		
				06J906026DA	06J906026DA	6987		
				06J906026DP	06J906026DP	6988		
				06J906026DN	06J906026DN	6989		
				06J906026DR	06J906026DR	6990		
				06J906021B	06J906021B	6991		
				06J906026DQ	06J906026DQ	6995		
2012	Jetta	2.0T CCTA CBFA	to correctly store ECM scan tool mode data	06J906027J	06J906027J	2907	24W1	366D
	Beetle	2.0T CCTA CBFA		06J906027K	06J906027K	2908		
				06J906027AG	06J906027AG	2906		
				06J906027CE	06J906027CE	2904		
				06J906027AE	06J906027AE	2909		
				06J906027CD	06J906027CD	2905		
				03H906023E	03H906023E	3013		
	Passat	3.6L CDVB						

Vehicle Updates

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM Unit</u>
2009-2011	Jetta Golf SportWagen	CBTA CBUA	Rough running behavior and cold start issues at certain conditions (under high electric power)	07K906055BE	07K906055BE	9213	24 10 04 24W4	3565
				07K906055BD	07K906055BD	9212		
				07K906055BC	07K906055BC	9210		
				07K906055BB	07K906055BB	9211		
				07K906055AG	07K906055AG	9970		
				07K906055AF	07K906055AF	9970		
				07K906055AJ	07K906055AJ	9970		
				07K906055AH	07K906055AH	9970		
				07K906055M	07K906055M	9970		
				07K906055N	07K906055N	9970		
				07K906055P	07K906055P	9970		
				07K906055Q	07K906055Q	9970		
				07K906055G	07K906055G	9217		
				07K906055F	07K906055F	9216		
				07K906055A	07K906055A	9214		
				07K906055	07K906055	9215		
2010	Touareg	3.6L BHK	Catalyst Monitoring	03H906032GQ	03H906032GQ	9893	24 12 05 24X5	35B1
2011	Jetta	2.0L CBPA	Idle w A/C on and slight hesitation	06G906055T	06G906055T	1205	24X7	3801
				06G906055R				
				06G906055B				
				06G906055AA	06G906055AA	1205		
				06G906055S		1205		
				06G906055C		1212		
				09G927750LE	09G927750LE	2330		
				09G927750LE	09G927750LE	2329		
2010-2013	Passat CC	2.0T CCTA CBFA	Current ECM/TCM programming may cause stumble depending on driving conditions	06J906027AB	06J906027AB	7378	24X8	3733
				06J906027AC	06J906027AC	9970		
				06J906027F	06J906027FE	3952		
				06J906027G	06J906027FD	3951		
				02E300058N	02E300058N	3509		

Vehicle Updates

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM Unit</u>
2011	Jetta	2.0L CBPA	slight hesitation concerns	06G906055T	06G906055T	1205	24Y4	3801
				06G906055AA	06G906055AA	1205		
				09G927750LE	09G927750LE	1791->2330		
				09G927750LE	09G927750LE	1975->2330		
				09G927750LE	09G927750LE	2040->2329		
				09G927750LE	09G927750LE	2174->2329		
2013	Jetta	1.4L CNLA	optimizes Hybrid system operation	04E906023	04E906023	5631	01 13 15 24Z5	384C
				5C0907080C	5C0907080C	0535		
2010-2012	Golf/GTI Jetta Eos CC Beetle	2.0T CJAA 2.0T CCTA CBFA	Customer states while braking and down shifting in Tiptronic mode the transmission does not respond accordingly. Customer states while accelerating from a rolling stop, the transmission does not respond accordingly.	02E300054M	02E300057B	2604->2730	37G2	364B
						2609->2730		
						2714->2730		
						2720->2730		
				02E300054M	02E300057B	2605->2731		
				02E300057B	02E300057B	2715->2731		
						2721->2731		
				02E300054J	02E300057A	2601->2705		
				02E300054L	02E300057C	2602->2724		
						2605->2724		
				02E300057C	02E300057C	2717->2724		
						2720->2724		
				02E300057B	02E300057B	2714->2730		
						2720->2730		
				02E300054C	02E300054C	2802->2806		
						2803->2806		
2013	CC	2.0T CCTA CBFA	DSG Software update	02E 300 058 N	02E 300 058 N	3522	37H3	3733
	Beetle					3523		
2012	Passat	All	Kessy Update	5K0959434A	5K0959434B	0802->0902	57E1	3639

Vehicle Updates

<u>Model Year</u>	<u>Model</u>	<u>Engine</u>	<u>Concern</u>	<u>Module Part #</u>	<u>New Part #</u>	<u>Updated Software Level</u>	<u>Technical Bulletin #</u>	<u>SVM Unit</u>
2013	Beetle Convertible	All	Convertible top update to improve top function see Bulletin for other model updates	5C3871601	5C3871601	0344	61B7	382F
2011	Jetta	All	The A/C system might not cool the vehicle fast enough or Key to lose adaption	5C0820047H	5C0820047M	103	87C6	345F
				5C0820047J	5C0820047N	103		
				5C0820047K	5C0820047P	103		
				5C0 820 047L	5C0 820 047Q	103		
2012	Tiguan Golf/GTI Sportwagen	All	Heater is not blowing hot enough	AC Module	See TB	0303->0404	87D3	36C8
						0304->0404		
2013	Tiguan Golf/GTI Beetle Passat Jetta CC	All	Radio Update Premium 8 from sw level 0007 to 0008 only, see bulletin	1K0035180AF	1K0035180AF	0007->0008	91J7	SD Card
2011	GTI Jetta Tiguan	All	Electronic Steering Column Lock w/ Kessy	5K0905861	5K0905861	120	28 11 01 96B7	3478