



Technical Service Bulletin

27 Repair Authorization - MY 24 BSG, Electrical Warning, DTC U046900 + B200096

27 24 66 2072960/1 February 9, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, Q7, SQ7, Q8, SQ8, and RS Q8	2024	All	Not Applicable

Condition

Customer states:

A yellow or red Electrical Supply warning is displayed in the instrument cluster.



Technical Service Bulletin



Figure 1: Cluster Warning Message.

Workshop findings:

One or more of the following DTCs may be stored in the Engine Electronics, J623 (address word 0001) and/or the Starter Generator, C29 (address word 00CC):

- **U046900:** Invalid Data Received From Starter / Generator Control Module – Symptom 36564 (Diagnostic Address 0001).
- **B200096:** Faulty control Module (Diagnostic address CC).

Technical Background



Technical Service Bulletin

In an effort to gain information on the DTC codes for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

- Verify the condition and document with images of the cluster.
- Identify the hardware part number in diagnostic address CC. Identify if the part number is either 4N1.903.028, 4N1.903.028.B or 4N0.903.028.S.
- If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Please attach the DTC, diagnostic log, and picture of the warning displayed in the cluster as shown in **Figure 1** to the TAC ticket.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (**2072960**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.