

Technical Service Bulletin



48 Power steering control module fault stored in Gateway (DTC U101D00)

48 14 60 2037710/1 July 10, 2014.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2015	All	Not applicable

Condition

- During diagnosis for unrelated repairs, the following DTC is logged in the Gateway, J533 (address word 19):
 - DTC U101D00 - 008** (Power steering control module - No communication)
- No warning light is illuminated, and there is no customer complaint.

Technical Background

There is a software issue with the power steering control unit that can lead to timed-out CAN messages. The issue only occurs when the ignition is switched off (terminal 15 off).

Production Solution

New software for the power steering control unit in preparation.

Service

If there is no complaint, no action is necessary. This DTC can be ignored and deleted.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB (2034221) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.