



Tech Tips

TT 87-13-01

Date: June 7, 2013

2013 Jetta Hybrid – A/C Inoperative, Fault B109EF0 “A/C compressor first run not performed”

If fault B109EF0 “A/C compressor first run not performed” is found in AW 08 A/C/heating Electronics, resolve fault by completing test plan “A/C compressor first run”. Test plan is available in VAS PC GFF through Function/Component selection or in ODIS 1.2.0 or later using the “Select self test” button on the Test plan tab.