



# Preliminary Information

## PIT6100A DTC B1141 Blazer EV

### Models

| Brand:    | Model:    | Model Years: | VIN: |     | Engine: | Transmissions: |
|-----------|-----------|--------------|------|-----|---------|----------------|
|           |           |              | from | to  |         |                |
| Chevrolet | Blazer EV | 2024         | All  | All | All     | All            |

|                            |                                                                |
|----------------------------|----------------------------------------------------------------|
| Involved Region or Country | North America                                                  |
| Condition                  | When checking for codes a dealer may find B1141 set in the BCM |
| Cause                      | Calibrations                                                   |

### Correction:

Reprogram the K9 Body Control Module.  
Clear all codes.  
If B1141 returns after programming the BCM follow diagnostics in SI.

### Additional SI Keywords

B1141, code, diagnostic, DTC, trouble

### Version History

|          |                                                             |
|----------|-------------------------------------------------------------|
| Version  | 2                                                           |
| Modified | 12/08/2023 - Created on.<br>03/18/2024- Updated Correction. |

