



Bulletin No.: PIT6226
Published date: 08/23/2024

Preliminary Information

PIT6226 Windshield Wipers Work On High Speed Only

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet Blazer EV	2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	CE1
Condition	Windshield wipers will work on high speed only. Wipers will not work on low speed or delay.
Cause	Incorrect B117A Windshield Outside Moisture Ambient Light and Humidity Sensor installed on vehicle. The vehicle may have had a B117A for a vehicle not equipped with rain sense installed instead of one for a vehicle that is equipped with rain sense.

Correction:
Check the part number on the B117A Windshield Outside Moisture Ambient Light and Humidity Sensor.
If the incorrect part number was installed install the correct sensor based on EPC.
If the correct part number is found already in the vehicle follow SI diagnostics.

Warranty Information

Version History

Version	1
Modified	08/23/2024 - Created on.