



STAR ONLINE PUBLICATION



Case Number: S2508000017 REV. A

Release Date: February 2025

Symptom/Vehicle Issue: Radio Frequency Hub (RFH) Module has an Active Diagnostic Trouble Code (DTC) B22A9-00 ECU Internal Performance

Technician Observation: RFH Module is setting an active DTC B22A9-00 Electronic Control Unit (ECU) Internal Performance with no customer complaints. **Do not replace RFH module see 1-3.**

1. Vehicle has RFH PN # 68671484AD
2. Active RFH DTC B22A9-00 ECU internal performance.
3. No functional issues observed or reported, **DTC cannot be cleared. DO NOT REPLACE THE RFH IF THERE ARE NO FUNCTIONAL ISSUES.**

Continue with normal diagnostics available if any functional issues are observed (or) If there are other active DTCs logged follow the diagnostics listed within service library.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.