



SSM 54226 2025 Navigator - Second Row Power Seats (Minor Feature Code BYBAL) - Second Row Seat Control Switch Does Not Move Seat Forward Or Backward

Some 2025 Navigator vehicles equipped with second row power seats (minor feature code BYBAL) may exhibit a symptom where the second row seat control switch does not move the seat forward or backward. There may also be diagnostic trouble code (DTC) B167F:11 stored in the rear LH power seat control module (SCMK) and/or the rear RH seat control module (SCML). To confirm a vehicle is built with minor feature code BYBAL, review the build information by double-clicking the vehicle identification number (VIN) in the upper left corner in the Professional Technician System (PTS). This may be due to the configuration of the SCMK and/or SCML modules. To resolve this condition, download and run the configuration applications "SCMK - Rear LH Power Seat Control Module [SCMK] Configuration" and the "SCML - Rear RH Power Seat Control Module [SCML] Configuration" using the latest version of the Ford Diagnosis and Repair System (FDRS). For claiming, use causal part 14F042 and labor operations 12651D and 12651D4.