

GPOP - Issue Review System

Part Number: 05190239A\$

Part Description: PIM Inverter

Issue Description: If the vehicle comes in with any of the following P codes, please refer to the active TSBs for HCP/AHCP flash BEFORE ordering PIM P0A78 - Drive Motor A Inverter Performance. P0A79 - Drive Motor B Inverter Performance. P0A3F-00 - Drive Motor A Position Sensor 1 Circuit. P0A43-00 - Drive Motor A Position Sensor Circuit Intermittent. P0A45-00 - Drive Motor B Position Sensor 1 Circuit. P0C1A-00 - Drive Motor B Torque Delivered Performance.